

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4519 5025	W184158 400 SEK	Toyota Celica -00 Parkeringshjälp Backsensor	1.8i 16V VT-1 143HK 1.8i 16V/4ZZ-FE 6VXL 2DR CPE BE 2ST BACKSENSORER+RELÄ	Vimmerby Bildemontering AB 0492-20028	9.393 A
5291 5025	W737609 200 SEK	Hyundai i30 -14 Parkeringshjälp Backsensor	1.6 CRDI KOMBI-SEDAN 110HK 1.6CRDI/D4FB 6VXL 5DR CS TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.668 A
5291 5025	W737610 200 SEK	Hyundai i30 -14 Parkeringshjälp Backsensor	1.6 CRDI KOMBI-SEDAN 110HK 1.6CRDI/D4FB 6VXL 5DR CS TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.668 A
5291 5025	W737611 200 SEK	Hyundai i30 -14 Parkeringshjälp Backsensor	1.6 CRDI KOMBI-SEDAN 110HK 1.6CRDI/D4FB 6VXL 5DR CS TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.668 A
4972 5025	W737216 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
4972 5025	W737213 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
4972 5025	W737215 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
4972 5025	W737217 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
4972 5025	W737218 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
4972 5025	W737214 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
4987 5025	W736314 150 SEK	VW Sharan -18 Parkeringshjälp Backsensor	2.0 TDI 4-MOTION MPV 184HK 2.0TDI/DFMA AUTOMAT/SCY TESTAD OK	Vimmerby Bildemontering AB 0492-20028	19.218 A
4987 5025	W736317 150 SEK	VW Sharan -18 Parkeringshjälp Backsensor	2.0 TDI 4-MOTION MPV 184HK 2.0TDI/DFMA AUTOMAT/SCY TESTAD OK	Vimmerby Bildemontering AB 0492-20028	19.218 A
5028 5025	W736086 200 SEK	Volvo V40 12-19 -16 Parkeringshjälp Backsensor	2.0 D3 DIESEL KOMBI 150HK 2.0ID4204T9 6VXL 5DR HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.391 A
5028 5025	W736085 200 SEK	Volvo V40 12-19 -16 Parkeringshjälp Backsensor	2.0 D3 DIESEL KOMBI 150HK 2.0ID4204T9 6VXL 5DR HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.391 A
5028 5025	W736087 200 SEK	Volvo V40 12-19 -16 Parkeringshjälp Backsensor	2.0 D3 DIESEL KOMBI 150HK 2.0ID4204T9 6VXL 5DR HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.391 A
5028 5025	W736084 200 SEK	Volvo V40 12-19 -16 Parkeringshjälp Backsensor	2.0 D3 DIESEL KOMBI 150HK 2.0ID4204T9 6VXL 5DR HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.391 A
4949 5025	W735838 200 SEK	VW Golf, e-Golf -19 Parkeringshjälp Backsensor	1.6 TDI DIESEL VARIANT 116HK 1.6/DGTE AUTOMAT 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.839 A
4949 5025	W735839 200 SEK	VW Golf, e-Golf -19 Parkeringshjälp Backsensor	1.6 TDI DIESEL VARIANT 116HK 1.6/DGTE AUTOMAT 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.839 A
4949 5025	W735842 200 SEK	VW Golf, e-Golf -19 Parkeringshjälp Backsensor	1.6 TDI DIESEL VARIANT 116HK 1.6/DGTE AUTOMAT 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.839 A
3862 5025	W735584 200 SEK	Renault Megane -18 Parkeringshjälp Backsensor	1.5 DCI DIESEL GRANDTOUR 110HK 1.5DCIK9K-657 6VXL 5 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	6.803 A
3862 5025	W735586 200 SEK	Renault Megane -18 Parkeringshjälp Backsensor	1.5 DCI DIESEL GRANDTOUR 110HK 1.5DCIK9K-657 6VXL 5 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	6.803 A
3862 5025	W735585 200 SEK	Renault Megane -18 Parkeringshjälp Backsensor	1.5 DCI DIESEL GRANDTOUR 110HK 1.5DCIK9K-657 6VXL 5 TESTAD OK	Vimmerby Bildemontering AB 0492-20028	6.803 A
3312 5025	W735182 200 SEK	Mercedes A-Class -13 Parkeringshjälp Backsensor	A180 1.5CDI MINIFLEX 109HK 1.5/OM607.951 6VXL 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.038 A
3312 5025	W735179 200 SEK	Mercedes A-Class -13 Parkeringshjälp Backsensor	A180 1.5CDI MINIFLEX 109HK 1.5/OM607.951 6VXL 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.038 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
3312 5025	W735181 200 SEK	Mercedes A-Class -13 Parkeringshjälp Backsensor	A180 1.5CDI MINIFLEX 109HK 1.5/OM607.951 6VXL 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.038 A
3312 5025	W735180 200 SEK	Mercedes A-Class -13 Parkeringshjälp Backsensor	A180 1.5CDI MINIFLEX 109HK 1.5/OM607.951 6VXL 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.038 A
4250 5025	W734523 250 SEK	Tesla Model S -16 Parkeringshjälp Backsensor	90D EL AWD KOMBI-SEDAN 525HK 90D/L2S 5DR CSE EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	28.432 A
4250 5025	W734522 250 SEK	Tesla Model S -16 Parkeringshjälp Backsensor	90D EL AWD KOMBI-SEDAN 525HK 90D/L2S 5DR CSE EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	28.432 A
4250 5025	W734526 250 SEK	Tesla Model S -16 Parkeringshjälp Backsensor	90D EL AWD KOMBI-SEDAN 525HK 90D/L2S 5DR CSE EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	28.432 A
4250 5025	W734525 250 SEK	Tesla Model S -16 Parkeringshjälp Backsensor	90D EL AWD KOMBI-SEDAN 525HK 90D/L2S 5DR CSE EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	28.432 A