

| BKod DKod | Lagernummer Pris | Fordon Del | Fordon Information Del Information | Företag Telefon | Mil Kvalité |
|--------------|-----------------------|--|--|--|----------------|
| 5564 7445 | W1073188 | KIA Rio -16 Spak Torkar / Spolaromkopplare | KIA RIO 1,2 SPECIAL EDITION 1.25 CVVT 86HK 5VXL 5DR | Norrbottns Bildemontering AB 0929-70000 | 4.024 A |
| 2709 7445 | W1073230 | Honda Jazz -12 Spak Torkar / Spolaromkopplare | HONDA JAZZ 1.4I 99HK AUT 5DR CSE BENSIN | Norrbottns Bildemontering AB 0929-70000 | 10.413 A |
| 3503 7445 | W1072985 | Opel Insignia -19 Spak Torkar / Spolaromkopplare | OPEL INSIGNIA SPORTS TOURER B16DTE 5DR CBI DIESEL | Norrbottns Bildemontering AB 0929-70000 | 2.586 A |
| 4208 7445 | W1072426 | Skoda Octavia -08 Spak Torkar / Spolaromkopplare | SKODA OCTAVIA AMB 1,6 BLF M 5DR CSE BENSIN | Norrbottns Bildemontering AB 0929-70000 | 12.742 A |
| 5046 7445 | W1072270 1.125 SEK | Volvo V90 Cross Country -21 Spak Torkar / Spolaromkopplare | VOLVO V90 CROSS COUNTRY D4204T14 A 5DR CBI DIESEL ENNDAST SPAK TORKAR/SPOL OMKOPPLARE | Norrbottns Bildemontering AB 0929-70000 | 9.810 A |
| 5073 7445 | W1071727 575 SEK | Volvo S60 -12 Spak Torkar / Spolaromkopplare | VOLVO S60 D5 AWD D5244T15 A 4DR SED DIESEL | Norrbottns Bildemontering AB 0929-70000 | 5.805 A |
| 2484 7445 | W1071830 | Ford Transit/Tourneo Courier -16 Spak Torkar / Spolaromkopplare | FORD TRANSIT COURIER UGCB M 5DR SKP DIESEL | Norrbottns Bildemontering AB 0929-70000 | 10.564 A |
| 5060 7445 | W1072065 250 SEK | Volvo 940 -91 Spak Torkar / Spolaromkopplare | VOLVO 944-852 GL B230FB T 4DR SED BENSIN SEDAN | Norrbottns Bildemontering AB 0929-70000 | 30.718 A |
| 5095 7445 | W1071265 | Volvo XC60 -19 Spak Torkar / Spolaromkopplare | VOLVO XC60 D4204T14 A 5DR SUV DIESEL ENDAST SPAK, PASSAR TILL SPAKCENTRAL: 32266885 | Norrbottns Bildemontering AB 0929-70000 | 17.425 A |
| 5008 7445 | W1071125 575 SEK | Volvo S60 -16 Spak Torkar / Spolaromkopplare | VOLVO S60 D4204T14 A 4DR SED DIESEL SVART | Norrbottns Bildemontering AB 0929-70000 | 11.286 A |
| 5203 7445 | W1070809 | Hyundai Getz -05 Spak Torkar / Spolaromkopplare | HYUNDAI GETZ 1,1 G4HD M 5DR CSE BENSIN | Norrbottns Bildemontering AB 0929-70000 | 18.508 A |
| 4976 7445 | W1070824 | VW Caddy -08 Spak Torkar / Spolaromkopplare | VW CADDY SKÅP BLS M 3DR SKP DIESEL | Norrbottns Bildemontering AB 0929-70000 | 21.751 A |
| 1446 7445 | W1070069 370 SEK | Dacia Dokker -15 Spak Torkar / Spolaromkopplare | DACIA DOKKER 1.5DCI 90HK 5VXL 5DR SKP DIESEL | Norrbottns Bildemontering AB 0929-70000 | 20.386 A |
| 1319 7445 | W1070035 160 SEK | Audi TT/TTS/TT RS -05 Spak Torkar / Spolaromkopplare | AUDI TT COUPÉ 3,2 Q BHE A 3DR CPE BENSIN | Norrbottns Bildemontering AB 0929-70000 | 14.928 A |
| 5390 7445 | W1070015 | Chatenet CH26 -13 Spak Torkar / Spolaromkopplare | CHATENET CH26 2CYL DIESEL 2DR MC DIESEL | Norrbottns Bildemontering AB 0929-70000 | 4.212 A* |
| 5085 7445 | W1069413 | Volvo XC40 -22 Spak Torkar / Spolaromkopplare | VOLVO XC40 B3154T9 A SUV | Norrbottns Bildemontering AB 0929-70000 | 3.491 A |
| 2729 7445 | W1068164 272 SEK | Honda Civic -08 Spak Torkar / Spolaromkopplare | HONDA CIVIC 5DR R18A2 A 5DR CSE BENSIN | Norrbottns Bildemontering AB 0929-70000 | 17.239 A |
| 5052 7445 | W1067715 475 SEK | Volvo C30 -08 Spak Torkar / Spolaromkopplare | VOLVO C30 D4204T M 3DR CSE DIESEL MED REGSENSOR | Norrbottns Bildemontering AB 0929-70000 | 19.611 A |
| 5070 7445 | W1067356 350 SEK | Volvo S40, V40 96-04 -04 Spak Torkar / Spolaromkopplare | VOLVO S40 B4184S2 M 4DR SED BENSIN 10 SITFT | Norrbottns Bildemontering AB 0929-70000 | 19.826 A |
| 5061 7445 | W1067254 462 SEK | Volvo V70 -01 Spak Torkar / Spolaromkopplare | VOLVO V70 B5244S2 M 5DR CBI BENSIN GRÅ | Norrbottns Bildemontering AB 0929-70000 | 24.901 A |
| 5050 7445 | W1067324 250 SEK | Volvo 740 -87 Spak Torkar / Spolaromkopplare | VOLVO 740 2.3i 5VXL 4DR SED BENSIN SEDAN | Norrbottns Bildemontering AB 0929-70000 | 43.106 A |
| 5059 7445 | W1067170 462 SEK | Volvo S80 -07 Spak Torkar / Spolaromkopplare | VOLVO S80 B6324S A 4DR SED BENSIN SOFT BEIGE FÖR REGSENSOR CH -113054 | Norrbottns Bildemontering AB 0929-70000 | 14.256 A |
| 2433 7445 | W1066990 270 SEK | Ford C-MAX, Ford Focus C-MAX -11 Spak Torkar / Spolaromkopplare | FORD C-MAX T3DB M 5DR MPV DIESEL | Norrbottns Bildemontering AB 0929-70000 | 18.419 A |
| 5025 7445 | W1066886 475 SEK | Volvo V50 -12 Spak Torkar / Spolaromkopplare | VOLVO V50 D4162T M 5DR CBI DIESEL MED REGSENSOR | Norrbottns Bildemontering AB 0929-70000 | 18.143 A |

| BKod DKod | Lagernummer Pris | Fordon Del | Fordon Information Del Information | Företag Telefon | Mil Kvalité |
|--------------|---------------------|--|--|---|----------------|
| 2707 7445 | W1066791 370 SEK | Honda Accord -07 Spak Torkar / Spolaromkopplare | HONDA ACCORD TOURER K20Z2 M 5DR CBI BENSIN 12 + 8 STIFT | Norrbottens Bildemontering AB 0929-70000 | 22.933 A |
| 3449 7445 | W1066574 370 SEK | Mitsubishi Outlander -20 Spak Torkar / Spolaromkopplare | MITSUBISHI OUTLANDER 4B12 A 5DR SUV ELHYBRID B | Norrbottens Bildemontering AB 0929-70000 | 4.174 A |
| 2426 7445 | W1066676 | Ford Focus -04 Spak Torkar / Spolaromkopplare | FORD FOCUS FYDH M 5DR CSE ETANOL E85 | Norrbottens Bildemontering AB 0929-70000 | 14.102 A |
| 4544 7445 | W1065698 397 SEK | Toyota Verso -12 Spak Torkar / Spolaromkopplare | TOYOTA VERSO 2ZR-FAE M 5DR CBI BENSIN | Norrbottens Bildemontering AB 0929-70000 | 19.650 A |
| 5061 7445 | W1065789 | Volvo V70 -01 Spak Torkar / Spolaromkopplare | VOLVO V70 B5244S M 5DR CBI BENSIN | Norrbottens Bildemontering AB 0929-70000 | 27.463 A |
| 5060 7445 | W1065576 250 SEK | Volvo 940 -91 Spak Torkar / Spolaromkopplare | VOLVO 944-852 GL 2.3i 5VXL 4DR SED BENSIN SEDAN | Norrbottens Bildemontering AB 0929-70000 | 40.997 A |