

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
8705 7268	W512795 500 SEK	Polaris Snöskoter -16 Knacksensor	SKS 800 155" 800CFI2 800CFI2	Lycksele Bildemontering AB 0950-12140	396 A
8702 7268	W509065 350 SEK	Lynx Snöskoter -14 Knacksensor	LYNX COMMANDER 800 E-TEC 800ETEC	Lycksele Bildemontering AB 0950-12140	726 A
8701 7268	W489357 350 SEK	Ski-Doo Snöskoter -17 Knacksensor	SUMMIT X 154 850 850ETEC 850ETEC	Lycksele Bildemontering AB 0950-12140	708 A
5063 7268	W477876 525 SEK	Volvo V70 -09 Knacksensor	V70 (III) B5254T8 5DR ETANOL E85	Lycksele Bildemontering AB 0950-12140	16.563 A
5314 7268	W474598 600 SEK	Seat Ibiza -16 Knacksensor	IBIZA CHZB 1,0TSI MAN 5VXL	Lycksele Bildemontering AB 0950-12140	4.054 A
1365 7268	W474002 250 SEK	Audi A5 -11 Knacksensor	S5 COUPE V8 4,2 QUATTRO CAUA V8 4,2 6 VXL QUATTRO SVART 1,2,5,6	Lycksele Bildemontering AB 0950-12140	10.754 A
1365 7268	W474000 250 SEK	Audi A5 -11 Knacksensor	S5 COUPE V8 4,2 QUATTRO CAUA V8 4,2 6 VXL QUATTRO BRUN 3,4,7,8	Lycksele Bildemontering AB 0950-12140	10.754 A
1365 7268	W473997 250 SEK	Audi A5 -11 Knacksensor	S5 COUPE V8 4,2 QUATTRO CAUA V8 4,2 6 VXL QUATTRO BRUN 3,4,7,8	Lycksele Bildemontering AB 0950-12140	10.754 A
1365 7268	W474001 250 SEK	Audi A5 -11 Knacksensor	S5 COUPE V8 4,2 QUATTRO CAUA V8 4,2 6 VXL QUATTRO SVART 1,2,5,6	Lycksele Bildemontering AB 0950-12140	10.754 A
8701 7268	W465483 350 SEK	Ski-Doo Snöskoter -11 Knacksensor	SUMMIT 600 E-TEC 146" 600ETEC 600ETEC	Lycksele Bildemontering AB 0950-12140	963 A
5576 7268	W459800 625 SEK	KIA Cee'd, Cee'd SW -19 Knacksensor	KIA CEED G4LD MANUELL 5DR KOMBI BENSIN KAMAXEL	Lycksele Bildemontering AB 0950-12140	126 A
5576 7268	W459799 625 SEK	KIA Cee'd, Cee'd SW -19 Knacksensor	KIA CEED G4LD MANUELL 5DR KOMBI BENSIN VEVAXEL	Lycksele Bildemontering AB 0950-12140	126 A
5586 7268	W385227 400 SEK	KIA Niro -17 Knacksensor	NIRO A EFTER KAT.	Lycksele Bildemontering AB 0950-12140	1.173 A
4951 7268	W384834 3.750 SEK	VW Passat -17 Knacksensor	PASSAT DFCA A	Lycksele Bildemontering AB 0950-12140	2.752 A
8705 7268	W368837 500 SEK	Polaris Snöskoter -13 Knacksensor	POLARIS 600 RMK 144 600CFI2 600CFI2	Lycksele Bildemontering AB 0950-12140	162 A
8705 7268	W358326 500 SEK	Polaris Snöskoter -13 Knacksensor	POLARIS 800 RMK ASSAULT 800CFI2	Lycksele Bildemontering AB 0950-12140	396 A
8705 7268	W356012 500 SEK	Polaris Snöskoter -07 Knacksensor	POLARIS 700 HO IQ DRAGON 700CFI4 BAND	Lycksele Bildemontering AB 0950-12140	1.216 A
8702 7268	W350853 500 SEK	Lynx Snöskoter -15 Knacksensor	LYNX 49 RANGER 600 E-TEC 600ETEC 600ETEC	Lycksele Bildemontering AB 0950-12140	327 A
8705 7268	W335682 500 SEK	Polaris Snöskoter -16 Knacksensor	PRO RMK 800 AXYS 800CFI2	Lycksele Bildemontering AB 0950-12140	105 A
8705 7268	W324270 500 SEK	Polaris Snöskoter -13 Knacksensor	POLARIS 800 SWITCHBACK P 800CFI2 800CFI2	Lycksele Bildemontering AB 0950-12140	289 A
8701 7268	W230377 350 SEK	Ski-Doo Snöskoter -06 Knacksensor	SKI-DOO SUMMIT 1000 HM SNÖSKOTER	Lycksele Bildemontering AB 0950-12140	922 A
4324 7268	W609027 625 SEK	Subaru Outback -22 Knacksensor	OUTBACK FB25 V 5DR STATIONSVAGN KOMBIVAGN ETANOLE VÄNSTER FRAM	Lycksele Bildemontering AB 0950-12140	2.453 A
4957 7268	W616620 400 SEK	VW Golf, e-Golf -21 Knacksensor	GOLF E-GOLF DPBA AUTOMAT 5DR STATIONSVAGN KOMBIVAGN	Lycksele Bildemontering AB 0950-12140	4.438 A*
5255 7268	W616301 775 SEK	Hyundai Ioniq -20 Knacksensor	IONIQ G4LE AUTOMAT 4DR SEDAN ELHYBRID BENSIN	Lycksele Bildemontering AB 0950-12140	1.903 A*

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4220 7268	W604836 562 SEK	Skoda Superb -21 Knacksensor	SUPERB DCEB AUTOMAT 5DR STATIONSVAGN KOMBIVAGN ELH	Lycksele Bildmontering AB 0950-12140	961 A*
4994 7268	W600515 375 SEK	VW Tiguan -20 Knacksensor	TIGUAN DKZA AUTOMAT 5DR SUV BENSIN	Lycksele Bildmontering AB 0950-12140	4.542 A*
4490 7268	W593106 500 SEK	Toyota RAV 4 -19 Knacksensor	TOYOTA RAV 4 KOMBI 5D 2019- A25A-FXS V 5DR SUV ELH	Lycksele Bildmontering AB 0950-12140	3.667 A*
4674 7268	W583535 500 SEK	Toyota Yaris -20 Knacksensor	YARIS M15A-FXE V 5DR KOMBI-SEDAN ELHYBRID BENSIN	Lycksele Bildmontering AB 0950-12140	2.401 A*
8701 7268	W379930 350 SEK	Ski-Doo Snöskoter -11 Knacksensor	800ETEC	Lycksele Bildmontering AB 0950-12140	691 A*
8702 7268	W232064 500 SEK	Lynx Snöskoter -09 Knacksensor	LYNX COMMANDER 600 600HO SDI	Lycksele Bildmontering AB 0950-12140	836 A*