

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
2499 5025	W723199 250 SEK	Ford Transit Connect/Tourneo Connect -22 Parkeringshjälp Backsensor	1.5 TDCI MINIFLEX SKÅP 120HK 1.5/ZTGA AUTOMAT 5DR S TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.802 A
2499 5025	W723198 250 SEK	Ford Transit Connect/Tourneo Connect -22 Parkeringshjälp Backsensor	1.5 TDCI MINIFLEX SKÅP 120HK 1.5/ZTGA AUTOMAT 5DR S TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.802 A
2499 5025	W723197 250 SEK	Ford Transit Connect/Tourneo Connect -22 Parkeringshjälp Backsensor	1.5 TDCI MINIFLEX SKÅP 120HK 1.5/ZTGA AUTOMAT 5DR S TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.802 A
2499 5025	W723200 250 SEK	Ford Transit Connect/Tourneo Connect -22 Parkeringshjälp Backsensor	1.5 TDCI MINIFLEX SKÅP 120HK 1.5/ZTGA AUTOMAT 5DR S TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.802 A
2499 5025	W720154 250 SEK	Ford Transit Connect/Tourneo Connect -22 Parkeringshjälp Backsensor	1.5 ECOBLUE DIESEL 110HK 1.5/Z2GA AUTOMAT 3DR SKP D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.824 A
2499 5025	W720153 250 SEK	Ford Transit Connect/Tourneo Connect -22 Parkeringshjälp Backsensor	1.5 ECOBLUE DIESEL 110HK 1.5/Z2GA AUTOMAT 3DR SKP D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.824 A
2499 5025	W720151 250 SEK	Ford Transit Connect/Tourneo Connect -22 Parkeringshjälp Backsensor	1.5 ECOBLUE DIESEL 110HK 1.5/Z2GA AUTOMAT 3DR SKP D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.824 A
2499 5025	W720152 250 SEK	Ford Transit Connect/Tourneo Connect -22 Parkeringshjälp Backsensor	1.5 ECOBLUE DIESEL 110HK 1.5/Z2GA AUTOMAT 3DR SKP D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.824 A
4217 5025	W728503	Skoda Kodiaq -22 Parkeringshjälp Backsensor	2.0 TDI 4X4 SUV 200HK 2.0TDI/DTUA AUTOMAT 5DR SUV D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.171 A
4217 5025	W728501	Skoda Kodiaq -22 Parkeringshjälp Backsensor	2.0 TDI 4X4 SUV 200HK 2.0TDI/DTUA AUTOMAT 5DR SUV D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.171 A
4217 5025	W728502	Skoda Kodiaq -22 Parkeringshjälp Backsensor	2.0 TDI 4X4 SUV 200HK 2.0TDI/DTUA AUTOMAT 5DR SUV D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.171 A
4217 5025	W728500	Skoda Kodiaq -22 Parkeringshjälp Backsensor	2.0 TDI 4X4 SUV 200HK 2.0TDI/DTUA AUTOMAT 5DR SUV D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.171 A
1549 5025	W648387 700 SEK	BMW X6 -21 Parkeringshjälp Backsensor	4.4T SUV 530HK 4.4iN63B44D AUTOMAT 5DR SUV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.438 A
1549 5025	W648386 700 SEK	BMW X6 -21 Parkeringshjälp Backsensor	4.4T SUV 530HK 4.4iN63B44D AUTOMAT 5DR SUV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.438 A
3344 5025	W701196 80 SEK	Mercedes E-Class 96->> -21 Parkeringshjälp Backsensor	E300 2.0DE DIESEL SEDAN 194HK 2.0DE/OM654.920 AUTOM TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.202 A
3344 5025	W701194 80 SEK	Mercedes E-Class 96->> -21 Parkeringshjälp Backsensor	E300 2.0DE DIESEL SEDAN 194HK 2.0DE/OM654.920 AUTOM TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.202 A
3344 5025	W701199 80 SEK	Mercedes E-Class 96->> -21 Parkeringshjälp Backsensor	E300 2.0DE DIESEL SEDAN 194HK 2.0DE/OM654.920 AUTOM TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.202 A
3344 5025	W701198 80 SEK	Mercedes E-Class 96->> -21 Parkeringshjälp Backsensor	E300 2.0DE DIESEL SEDAN 194HK 2.0DE/OM654.920 AUTOM TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.202 A
3344 5025	W701195 80 SEK	Mercedes E-Class 96->> -21 Parkeringshjälp Backsensor	E300 2.0DE DIESEL SEDAN 194HK 2.0DE/OM654.920 AUTOM TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.202 A
3344 5025	W701197 80 SEK	Mercedes E-Class 96->> -21 Parkeringshjälp Backsensor	E300 2.0DE DIESEL SEDAN 194HK 2.0DE/OM654.920 AUTOM TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.202 A
4972 5025	W737213 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
4972 5025	W737216 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
4972 5025	W737214 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
4972 5025	W737217 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4972 5025	W737218 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
4972 5025	W737215 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	2.0TDI 4-MOTION MINIFLEX 150HK 2.0TDI/DFSB AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.006 A
2499 5025	W724679 250 SEK	Ford Transit Connect/Tourneo Connect -20 Parkeringshjälp Backsensor	1.5 ECOBLUE DIESEL SKÅP 101HK 1.5/ZZGA AUTOMAT 3DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	4.478 A
2499 5025	W724682 250 SEK	Ford Transit Connect/Tourneo Connect -20 Parkeringshjälp Backsensor	1.5 ECOBLUE DIESEL SKÅP 101HK 1.5/ZZGA AUTOMAT 3DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	4.478 A
2499 5025	W724681 250 SEK	Ford Transit Connect/Tourneo Connect -20 Parkeringshjälp Backsensor	1.5 ECOBLUE DIESEL SKÅP 101HK 1.5/ZZGA AUTOMAT 3DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	4.478 A
2499 5025	W724680 250 SEK	Ford Transit Connect/Tourneo Connect -20 Parkeringshjälp Backsensor	1.5 ECOBLUE DIESEL SKÅP 101HK 1.5/ZZGA AUTOMAT 3DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	4.478 A