

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
3826 4530	W10293 400 SEK	Renault Clio -15 Kolkkanister Ventil	5DR CBI 0.9 TCE	Ericssons Bildemontering AB 0370-28100	6.543 A
1356 4530	W24536 300 SEK	Audi Q5 -13 Kolkkanister Ventil	5DR SUV 2.0TDI AUTO TURBO INTERCOOLNER DAMPER	Ericssons Bildemontering AB 0370-28100	16.480 A
4953 4530	W93853 500 SEK	VW Polo -18 Kolkkanister Ventil	5DR CC 1.0TSI 5VXL	Ericssons Bildemontering AB 0370-28100	9.105 A
3418 4530	W93357 400 SEK	Mitsubishi Colt -09 Kolkkanister Ventil	5DR CC 1.3 16 5VXL	Ericssons Bildemontering AB 0370-28100	15.059 A
3826 4530	W60865 400 SEK	Renault Clio -14 Kolkkanister Ventil	5DR CC 0,9TCE 5VXL	Ericssons Bildemontering AB 0370-28100	6.743 A
3622 4530	W46514 300 SEK	Peugeot 2008 -14 Kolkkanister Ventil	5DR CBI 1.2 VTI 5VXL	Ericssons Bildemontering AB 0370-28100	14.530 A
1507 4530	W16287 250 SEK	BMW X3 -05 Kolkkanister Ventil	5DR SUV 2,5I AUTO 4WD	Ericssons Bildemontering AB 0370-28100	32.038 A
5060 4530	W92822 200 SEK	Volvo 940 -96 Kolkkanister Ventil	4DRSED 2.3T 5VXL	Ericssons Bildemontering AB 0370-28100	28.958 A
4411 4530	W8555 400 SEK	Suzuki SX4 S-Cross -15 Kolkkanister Ventil	5DR CC 1.6L 5VXL AWD SX4	Ericssons Bildemontering AB 0370-28100	8.085 A
4573 4530	W15999 250 SEK	Toyota Avensis -04 Kolkkanister Ventil	5DR CBI 2.0 5VXL	Ericssons Bildemontering AB 0370-28100	21.565 A
4479 4530	W34083 300 SEK	Suzuki Grand Vitara -99 Kolkkanister Ventil	5DR SUV 2.5 5VXL	Ericssons Bildemontering AB 0370-28100	11.769 A
4710 4530	W88449 400 SEK	Mini One/Cooper R50/53 -02 Kolkkanister Ventil	2DR CC 1.6 5VXL	Ericssons Bildemontering AB 0370-28100	16.520 A
4036 4530	W83543 150 SEK	Saab 9-3 -06 Kolkkanister Ventil	5DR CBI 2.0AERO AUTO	Ericssons Bildemontering AB 0370-28100	21.576 A
3333 4530	W66175 300 SEK	Mercedes C-Class -03 Kolkkanister Ventil	5DR CBI C180 KOM AUTO	Ericssons Bildemontering AB 0370-28100	29.167 A
4219 4530	W26191 500 SEK	Skoda Yeti -10 Kolkkanister Ventil	5DR SUV 1.8TSI 6VXL AWD	Ericssons Bildemontering AB 0370-28100	12.305 A
4914 4530	W78610 300 SEK	VW Golf, e-Golf -05 Kolkkanister Ventil	5DR CC 1.6 5VXL	Ericssons Bildemontering AB 0370-28100	18.188 A
3616 4530	W77747 300 SEK	Peugeot 206 -09 Kolkkanister Ventil		Ericssons Bildemontering AB 0370-28100	- A
4352 4530	W67746 650 SEK	Subaru XV -18 Kolkkanister Ventil	5DR CBI	Ericssons Bildemontering AB 0370-28100	10 A
3701 4530	W24378 550 SEK	Porsche Boxster -98 Kolkkanister Ventil	2DR CUPE 2,5 5VXL	Ericssons Bildemontering AB 0370-28100	13.708 A
4479 4530	W7024 295 SEK	Suzuki Grand Vitara -05 Kolkkanister Ventil	5DR CBI/SUV 2,7 V6 AUTO	Ericssons Bildemontering AB 0370-28100	16.427 A
3418 4530	W4461 295 SEK	Mitsubishi Colt -11 Kolkkanister Ventil	5DR CC 1,3 5VXL	Ericssons Bildemontering AB 0370-28100	7.158 A
4578 4530	W48566 275 SEK	Toyota RAV 4 -03 Kolkkanister Ventil	5DR CBI 2.0 VVTI 4WD 5VXL	Ericssons Bildemontering AB 0370-28100	23.019 A
4479 4530	W48536 375 SEK	Suzuki Grand Vitara -04 Kolkkanister Ventil	5DR SUV 2,5 24V V6 5VXL4WD	Ericssons Bildemontering AB 0370-28100	22.446 A
1314 4530	W41653 95 SEK	Audi 80, 90, 85-91 -89 Kolkkanister Ventil	4DR 2,3 5VX AC ABS	Ericssons Bildemontering AB 0370-28100	25.225 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
2779 4530	W9152 150 SEK	Honda CR-V -03 Kolkkanister Ventil	4 DR SUV AUT 2,0 16V	Ericssons Bildemontering AB 0370-28100	20.956