

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4422 5076	W98064 200 SEK	Suzuki Swift -11 Spolarpump Baklucka	5DR CC 1,2GLX 2WD 5VXL	Ericssons Bildemontering AB 0370-28100	11.601 A
1507 5076	W97349 200 SEK	BMW X3 -07 Spolarpump Baklucka	5DR SUV 3.0D AUTO	Ericssons Bildemontering AB 0370-28100	24.923 A
1507 5076	W97407 200 SEK	BMW X3 -07 Spolarpump Baklucka	5DR SUV 3.0D AUTO	Ericssons Bildemontering AB 0370-28100	24.923 A
4528 5076	W61691 200 SEK	Toyota Yaris -12 Spolarpump Baklucka	5DR CC 1,3 16V AUTDOHC EFI	Ericssons Bildemontering AB 0370-28100	5.495 A
4329 5076	W58417 200 SEK	Subaru Legacy -12 Spolarpump Baklucka	4DR SED 2,0D 6VXL AWD	Ericssons Bildemontering AB 0370-28100	15.718 A
4568 5076	W37099 200 SEK	Toyota Avensis -08 Spolarpump Baklucka	5DR CBI 2.0I 16V	Ericssons Bildemontering AB 0370-28100	22.788 A
1507 5076	W17573 200 SEK	BMW X3 -05 Spolarpump Baklucka	5DR SUV 2,5I AUTO 4WD	Ericssons Bildemontering AB 0370-28100	32.038 A
1529 5076	W21360 150 SEK	BMW 3-Series -07 Spolarpump Baklucka	5DR CBI 325D AUT145KW	Ericssons Bildemontering AB 0370-28100	25.492 A
4544 5076	W93201 200 SEK	Toyota Verso -09 Spolarpump Baklucka	5DR CBI 1.8 16V 6VXL	Ericssons Bildemontering AB 0370-28100	18.451 A
1516 5076	W90301 200 SEK	BMW X1 -10 Spolarpump Baklucka	5DR SUV 2,0D 4WD 6VXL FELMEDELANDE ANTISSPIN	Ericssons Bildemontering AB 0370-28100	32.831 A
4527 5076	W86755 150 SEK	Toyota Yaris -11 Spolarpump Baklucka	DR CC 1.33 VVT-I AUTO	Ericssons Bildemontering AB 0370-28100	4.558 A
1529 5076	W86587 150 SEK	BMW 3-Series -08 Spolarpump Baklucka	5DR CBI 320I 6VXL125KW	Ericssons Bildemontering AB 0370-28100	27.600 A
3210 5076	W879 150 SEK	Mazda 6 -06 Spolarpump Baklucka	5DR CBI 2,0 16V 6VXL	Ericssons Bildemontering AB 0370-28100	13.253 A
3966 5076	W85532 500 SEK	LandRover Discovery -15 Spolarpump Baklucka	5DR SUV 2.2L CRDI 16 AUTO	Ericssons Bildemontering AB 0370-28100	5.520 A
4573 5076	W74902 100 SEK	Toyota Avensis -06 Spolarpump Baklucka	5DR CBI 1.8 5VXL	Ericssons Bildemontering AB 0370-28100	19.914 A
4026 5076	W83526 150 SEK	Saab 9-5 -06 Spolarpump Baklucka	5DR CBI 2.3T AERO 6VXL	Ericssons Bildemontering AB 0370-28100	25.448 A
4548 5076	W82166 300 SEK	Toyota Prius -14 Spolarpump Baklucka	5DR CBI 1,8 AUT	Ericssons Bildemontering AB 0370-28100	13.182 A
4308 5076	W5145 200 SEK	Subaru Outback -03 Spolarpump Baklucka	5DR CBI 2.5AWD AUTO	Ericssons Bildemontering AB 0370-28100	35.936 A
4352 5076	W26949 300 SEK	Subaru XV -18 Spolarpump Baklucka	5DR CBI	Ericssons Bildemontering AB 0370-28100	10 A
4303 5076	W28582 200 SEK	Subaru Outback -10 Spolarpump Baklucka	5DR CBI 2,0D 6VXLMOTOR KASS	Ericssons Bildemontering AB 0370-28100	28.732 A
3333 5076	W64853 150 SEK	Mercedes C-Class -05 Spolarpump Baklucka	5DR CBI 180KOMPRESOR AUTO	Ericssons Bildemontering AB 0370-28100	25.310 A
4303 5076	W81539 150 SEK	Subaru Outback -10 Spolarpump Baklucka	5DR CBI 2.0D 6VXL	Ericssons Bildemontering AB 0370-28100	27.500 A
4539 5076	W1785 200 SEK	Toyota Corolla Verso -08 Spolarpump Baklucka	5DR CBI 1.8 5VXL	Ericssons Bildemontering AB 0370-28100	13.853 A
4036 5076	W782 150 SEK	Saab 9-3 -07 Spolarpump Baklucka	5DR CBI 1.9TDI 6VXL	Ericssons Bildemontering AB 0370-28100	21.672 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4422 5076	W33642 150 SEK	Suzuki Swift -11 Spolarpump Baklucka	5DR CC 1.2 5VXL	Ericssons Bildemontering AB 0370-28100	5.955 A
4037 5076	W40402 200 SEK	Saab 9-3 -11 Spolarpump Baklucka	5DR CBI 2.0T BIOP 6VXL	Ericssons Bildemontering AB 0370-28100	15.065 A
4408 5076	W43751 150 SEK	Suzuki SX4 -07 Spolarpump Baklucka	5DR CC 1,6 5VXL 295985	Ericssons Bildemontering AB 0370-28100	19.899 A
4036 5076	W58184 150 SEK	Saab 9-3 -07 Spolarpump Baklucka	5DR CBI 1.9D AUTO	Ericssons Bildemontering AB 0370-28100	28.991 A
4037 5076	W59792 150 SEK	Saab 9-3 -10 Spolarpump Baklucka	5DR CBI 1.8T AUTO	Ericssons Bildemontering AB 0370-28100	14.045 A
4553 5076	W23119 150 SEK	Toyota Corolla -04 Spolarpump Baklucka	5DR CC 1.6 VVTI 5VXL	Ericssons Bildemontering AB 0370-28100	18.105 A