

| BKod DKod | Lagernummer Pris | Fordon Del | Fordon Information Del Information | Företag Telefon | Mil Kvalité |
|--------------|---------------------|---|---|---|----------------|
| 2202 7840 | W99537 300 SEK | Fiat 500 -12 Vindrute torkararm / armar | 3DR CC 1.2MPI 5VXL | Ericssons Bildemontering AB 0370-28100 | 11.570 A |
| 3319 7840 | W98825 200 SEK | Mercedes SLK-Class -08 Vindrute torkararm / armar | 2DR CAB 200 K AUTO HF | Ericssons Bildemontering AB 0370-28100 | 23.551 A |
| 3334 7840 | W52742 300 SEK | Mercedes C-Class -11 Vindrute torkararm / armar | 5DR CBI C220 2.2 CDI AUTOC 220 CDI BLUEEFFICIENCY | Ericssons Bildemontering AB 0370-28100 | 24.127 A |
| 3954 7840 | W76470 400 SEK | LandRover Discovery -06 Vindrute torkararm / armar | 5DR SUV 2.7 TD AUTOVF HJUL SKADAD | Ericssons Bildemontering AB 0370-28100 | 25.345 A |
| 5052 7840 | W87555 300 SEK | Volvo C30 -07 Vindrute torkararm / armar | 3DR 1.8 5VXL | Ericssons Bildemontering AB 0370-28100 | 30.110 A |
| 4949 7840 | W33689 150 SEK | VW Golf, e-Golf -17 Vindrute torkararm / armar | 5DR 1.4 TSI AUTO VF | Ericssons Bildemontering AB 0370-28100 | 2.915 A |
| 4929 7840 | W59289 300 SEK | VW Passat -14 Vindrute torkararm / armar | 5DR CBI 2.0TDI AUTO 4WD 3AB 955 410 | Ericssons Bildemontering AB 0370-28100 | 23.411 A |
| 4569 7840 | W7468 300 SEK | Toyota Avensis -12 Vindrute torkararm / armar | 5DR CBI 2.2 D-4D AUTO 8522105090 | Ericssons Bildemontering AB 0370-28100 | 22.730 A |
| 1540 7840 | W85779 300 SEK | BMW 5-Series -13 Vindrute torkararm / armar | 4DR SED 520 2.0D 6VXL 61 61 7 203 156 | Ericssons Bildemontering AB 0370-28100 | 25.790 A |
| 1746 7840 | W36414 300 SEK | Citroen C4 Cactus -18 Vindrute torkararm / armar | 5DR CC 1.2 THP 5VXL 16 118 715 80 | Ericssons Bildemontering AB 0370-28100 | 8.696 A |
| 5015 7840 | W78403 500 SEK | Volvo V60 Cross Country -19 Vindrute torkararm / armar | 5DR CBI 2.0D4 AUTO CROSS 31693538 | Ericssons Bildemontering AB 0370-28100 | 10.042 A |
| 4973 7840 | W74439 300 SEK | VW Caddy -15 Vindrute torkararm / armar | 5DR SKÅP 1.6TDI AUTO 2K2 955 410 B | Ericssons Bildemontering AB 0370-28100 | 21.557 A |
| 3343 7840 | W34199 300 SEK | Mercedes E-Class 96->> -13 Vindrute torkararm / armar | 4DR SED 200CDI AUTBLUEEFFICIENCY A 212 820 13 44 | Ericssons Bildemontering AB 0370-28100 | 13.989 A |
| 5442 7840 | W10434 200 SEK | Ligier JS 50 -20 Vindrute torkararm / armar | 3DR | Ericssons Bildemontering AB 0370-28100 | 4.844 A |
| 3646 7840 | W14680 300 SEK | Peugeot 508 -12 Vindrute torkararm / armar | 5DR CBI 1.6 HDI 5VXL 9686437680 | Ericssons Bildemontering AB 0370-28100 | 23.141 A |
| 4984 7840 | W60027 300 SEK | VW Tiguan -14 Vindrute torkararm / armar | 5DR SUV 2,0TDI AUT 4WD 5N1 955 410 | Ericssons Bildemontering AB 0370-28100 | 12.917 A |
| 4976 7840 | W60021 300 SEK | VW Caddy -10 Vindrute torkararm / armar | 5DR SKÅP 1.9TDI 5VXL 2K1 955 410 A | Ericssons Bildemontering AB 0370-28100 | 21.663 A |
| 3334 7840 | W59397 300 SEK | Mercedes C-Class -12 Vindrute torkararm / armar | 5DR CBI 1.8I AUTO A 204 820 15 44 | Ericssons Bildemontering AB 0370-28100 | 17.733 A |
| 4303 7840 | W32469 300 SEK | Subaru Outback -14 Vindrute torkararm / armar | 5DR CBI 2.0D AUTO 86532AJ060 | Ericssons Bildemontering AB 0370-28100 | 18.671 A |
| 5075 7840 | W24812 300 SEK | Volvo XC60 -09 Vindrute torkararm / armar | 5DR SUV 2.4 D MK1 6VXL 30753525 | Ericssons Bildemontering AB 0370-28100 | 33.691 A |
| 3622 7840 | W3758 300 SEK | Peugeot 2008 -14 Vindrute torkararm / armar | 5DR CBI 1.2 VTI 5VXL 16 083 927 80 | Ericssons Bildemontering AB 0370-28100 | 14.530 A |
| 4976 7840 | W89519 300 SEK | VW Caddy -09 Vindrute torkararm / armar | 5DR SKÅP 1.9TDI 5VXL 2K1 955 410 A | Ericssons Bildemontering AB 0370-28100 | 19.149 A |
| 4950 7840 | W38227 300 SEK | VW Crafter, e-Crafter -15 Vindrute torkararm / armar | 2DR 2,0D 6VXL 35 FLAKENKELHYTT 105/120KW 2E1 955 402 A | Ericssons Bildemontering AB 0370-28100 | 27.923 A |
| 2174 7840 | W65220 300 SEK | Nissan Qashqai -11 Vindrute torkararm / armar | 5DR SUV 1.6 5VXL | Ericssons Bildemontering AB 0370-28100 | 25.189 A |

| BKod DKod | Lagernummer Pris | Fordon Del | Fordon Information Del Information | Företag Telefon | Mil Kvalité |
|--------------|---------------------|---|---------------------------------------|---|----------------|
| 1520 7840 | W26418 300 SEK | BMW 1-Series -05 Vindrute torkarm / armar | 5DR CC 1.6 5VXL 61 61 9 450 004 | Ericssons Bildemontering AB 0370-28100 | 28.550 A |
| 5075 7840 | W75422 300 SEK | Volvo XC60 -09 Vindrute torkarm / armar | 5DR SUV 2.4D5 6VXL 30753526 | Ericssons Bildemontering AB 0370-28100 | 26.153 A |
| 4914 7840 | W66711 200 SEK | VW Golf, e-Golf -05 Vindrute torkarm / armar | 5DR CC 1.6 5VXL 1K1 955 409 | Ericssons Bildemontering AB 0370-28100 | 26.362 A |
| 3502 7840 | W44420 300 SEK | Opel Insignia -10 Vindrute torkarm / armar | 4DR SED 1.8 6VXL 13227398 | Ericssons Bildemontering AB 0370-28100 | 21.110 A |
| 4973 7840 | W1463 300 SEK | VW Caddy -13 Vindrute torkarm / armar | 5DR SKÅP 1.6TDI 5VXL 2K1 955 410 B | Ericssons Bildemontering AB 0370-28100 | 9.278 A |
| 4914 7840 | W37603 300 SEK | VW Golf, e-Golf -08 Vindrute torkarm / armar | 5DR CC 1.4TSI 1Q1 955 410 | Ericssons Bildemontering AB 0370-28100 | 22.733 A |