

| BKod DKod | Lagernummer Pris | Fordon Del | Fordon Information Del Information | Företag Telefon | Mil Kvalité |
|--------------|---------------------|---|--|---|----------------|
| 4555 5013 | W99681 2.500 SEK | Toyota Yaris -15 Baklucka CC / Kombi-Sedan | 5DR CC 1.33 AUTO | Ericssons Bildemontering AB 0370-28100 | 6.459 |
| 2202 5013 | W46264 2.500 SEK | Fiat 500 -12 Baklucka CC / Kombi-Sedan | 3DR CC 1.2MPI 5VXL UTAN TORKARMOTOPR OCH LÅSKISTA | Ericssons Bildemontering AB 0370-28100 | 11.570 A |
| 5028 5013 | W99314 2.500 SEK | Volvo V40 12-19 -14 Baklucka CC / Kombi-Sedan | 5DR CC 1.6 D2 6VXL UTAN TORKARMOTOR OCH LÅSKISTA | Ericssons Bildemontering AB 0370-28100 | 19.946 A |
| 1142 5013 | W99229 2.000 SEK | Alfa 156 -03 Baklucka CC / Kombi-Sedan | 5DR CC 2.0 5VXL | Ericssons Bildemontering AB 0370-28100 | 14.500 A |
| 4949 5013 | W99335 2.500 SEK | VW Golf, e-Golf -13 Baklucka CC / Kombi-Sedan | 5DR CC 1.6TDI 6VXL UTAN BAKLJUS OCH TORKARMOTOR | Ericssons Bildemontering AB 0370-28100 | 20.447 A |
| 1529 5013 | W99318 2.000 SEK | BMW 3-Series -07 Baklucka CC / Kombi-Sedan | 4DR SED 330 3.0XI AUTO | Ericssons Bildemontering AB 0370-28100 | 19.280 A |
| 3308 5013 | W98955 3.000 SEK | Mercedes B-Class -05 Baklucka CC / Kombi-Sedan | 5DR CC 1.5I 5VXL | Ericssons Bildemontering AB 0370-28100 | 20.492 |
| 5318 5013 | W98918 1.250 SEK | Seat Mii -13 Baklucka CC / Kombi-Sedan | 3DR CC 1.0 5VXL | Ericssons Bildemontering AB 0370-28100 | 17.852 |
| 4956 5013 | W98816 4.000 SEK | VW Golf Sportsvan -18 Baklucka CC / Kombi-Sedan | 5DR CC 1.2TSI 6VXL | Ericssons Bildemontering AB 0370-28100 | 9.222 |
| 4949 5013 | W98753 3.000 SEK | VW Golf, e-Golf -14 Baklucka CC / Kombi-Sedan | 5DR CC 1.4 TSI 6VXL | Ericssons Bildemontering AB 0370-28100 | 28.836 A |
| 4710 5013 | W35875 4.500 SEK | Mini One/Cooper R50/53 -04 Baklucka CC / Kombi-Sedan | 3DR CC 1.6 5VXL | Ericssons Bildemontering AB 0370-28100 | 21.760 A* |
| 1319 5013 | W98360 5.000 SEK | Audi TT/TTS/TT RS -00 Baklucka CC / Kombi-Sedan | 3DR 1.8 TURBO 5VXL | Ericssons Bildemontering AB 0370-28100 | 18.153 A |
| 4937 5013 | W98204 3.000 SEK | VW Polo -12 Baklucka CC / Kombi-Sedan | 5DR CC 1.4 5VXL | Ericssons Bildemontering AB 0370-28100 | 12.126 |
| 4548 5013 | W73935 2.500 SEK | Toyota Prius -13 Baklucka CC / Kombi-Sedan | 5DR CC 1,8 AUT HYBRIDELHYBRID UTAN BAKRUTA | Ericssons Bildemontering AB 0370-28100 | 33.478 A* |
| 4908 5013 | W1795 2.000 SEK | VW Golf, e-Golf -09 Baklucka CC / Kombi-Sedan | 5DR CC 1.4TSI 6VXL | Ericssons Bildemontering AB 0370-28100 | 16.289 |
| 5052 5013 | W23793 2.000 SEK | Volvo C30 -07 Baklucka CC / Kombi-Sedan | 3DR 1.8 5VXL UTAN TORKARMOTOR OCH BROMLJUS | Ericssons Bildemontering AB 0370-28100 | 30.110 A |
| 5052 5013 | W45271 1.850 SEK | Volvo C30 -08 Baklucka CC / Kombi-Sedan | 5DR CC 1.8 F 5VXL | Ericssons Bildemontering AB 0370-28100 | 19.445 A |
| 4934 5013 | W5267 1.000 SEK | VW Polo -06 Baklucka CC / Kombi-Sedan | 5DR CC 1.4 5VXL UTAN TORKARMOTOR OCH LÅSKISTA | Ericssons Bildemontering AB 0370-28100 | 13.822 A |
| 5562 5013 | W80834 2.500 SEK | KIA Venga -10 Baklucka CC / Kombi-Sedan | 5DR CC 1.4 5VXL | Ericssons Bildemontering AB 0370-28100 | 8.795 A |
| 4212 5013 | W63082 1.650 SEK | Skoda Fabia -08 Baklucka CC / Kombi-Sedan | 5DR CC 1.2 5VXL UTAN LÅSKISTA | Ericssons Bildemontering AB 0370-28100 | 16.125 A |
| 5442 5013 | W69118 3.000 SEK | Ligier JS 50 -18 Baklucka CC / Kombi-Sedan | 5DR CC PROGRESS | Ericssons Bildemontering AB 0370-28100 | 3.079 A |
| 1345 5013 | W24591 1.500 SEK | Audi A3, S3 -11 Baklucka CC / Kombi-Sedan | 5DR CC 1.6TDI 5VXL | Ericssons Bildemontering AB 0370-28100 | 14.453 A* |
| 2450 5013 | W97624 4.950 SEK | Ford Mondeo -13 Baklucka CC / Kombi-Sedan | 5DR SED 2.0 TDCI 6VXL UTAN TORKARMOTORT OCH BAKLJUS | Ericssons Bildemontering AB 0370-28100 | 31.788 A |
| 4949 5013 | W97773 3.000 SEK | VW Golf, e-Golf -16 Baklucka CC / Kombi-Sedan | 5DR CC 1.6TDI 5VXL UTAN BROMLJUS | Ericssons Bildemontering AB 0370-28100 | 7.165 A |

| BKod DKod | Lagernummer Pris | Fordon Del | Fordon Information Del Information | Företag Telefon | Mil Kvalité |
|--------------|---------------------|--|---|---|----------------|
| 5029 5013 | W27185 2.500 SEK | Volvo V40 Cross Country -18 Baklucka CC / Kombi-Sedan | 5DR CC 1.5 AUTO | Ericssons Bildemontering AB 0370-28100 | 9.797 A |
| 5291 5013 | W93138 2.500 SEK | Hyundai i30 -15 Baklucka CC / Kombi-Sedan | 5DR CC 1.4 6VXL UTAN BROMLJUS | Ericssons Bildemontering AB 0370-28100 | 7.316 A* |
| 3514 5013 | W1035 1.750 SEK | Opel Corsa -10 Baklucka CC / Kombi-Sedan | 5DR CC 1.2 AUTO UTAN BROMSLJUS BAKRUTA | Ericssons Bildemontering AB 0370-28100 | 17.697 A |
| 5028 5013 | W84634 2.500 SEK | Volvo V40 12-19 -15 Baklucka CC / Kombi-Sedan | 5DR CC 1.6 D2 6VXL | Ericssons Bildemontering AB 0370-28100 | 12.841 A |
| 1746 5013 | W66716 7.500 SEK | Citroen C4 Cactus -18 Baklucka CC / Kombi-Sedan | 5DR CC 1.2 THP 5VXL UTAN BROMLJUS | Ericssons Bildemontering AB 0370-28100 | 8.696 A |
| 2718 5013 | W4628 2.500 SEK | Honda Insight -10 Baklucka CC / Kombi-Sedan | 5DR CC 1.3V-TEC HYBR AUTO UTAN RUTTA | Ericssons Bildemontering AB 0370-28100 | 10.276 A |