

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4984 7425	W31672 200 SEK	VW Tiguan -08 Spolarpump Vindruta	5DR SUV 2.0 6VXL 4WD	Ericssons Bildemontering AB 0370-28100	26.542 A
5024 7425	W99905 150 SEK	Volvo V50 -05 Spolarpump Vindruta	5DR CBI T5 2.5 MK1 AUTO	Ericssons Bildemontering AB 0370-28100	24.451 A
3561 7425	W99726 150 SEK	Opel Zafira -06 Spolarpump Vindruta	5DR CBI 1.8 5VXL	Ericssons Bildemontering AB 0370-28100	14.889 A
5028 7425	W59338 250 SEK	Volvo V40 12-19 -14 Spolarpump Vindruta	5DR CC 1.6 D2 6VXL	Ericssons Bildemontering AB 0370-28100	19.946 A
3821 7425	W39846 250 SEK	Renault Zoe -18 Spolarpump Vindruta	5DR CC R110 ZE40 MK1 AUTO	Ericssons Bildemontering AB 0370-28100	4.391 A
3214 7425	W97577 200 SEK	Mazda 2 -14 Spolarpump Vindruta	5DR CC 1.3 5VXL	Ericssons Bildemontering AB 0370-28100	12.691 A
3691 7425	W84687 150 SEK	Peugeot Partner -17 Spolarpump Vindruta	5DR SKÅP 1.6 HDI 6VXL	Ericssons Bildemontering AB 0370-28100	5.159 A
3622 7425	W32005 200 SEK	Peugeot 2008 -16 Spolarpump Vindruta	5DR CBI 1.2 VTI CROS AUTO	Ericssons Bildemontering AB 0370-28100	9.016 A
4908 7425	W99390 200 SEK	VW Golf, e-Golf -12 Spolarpump Vindruta	5DR CBI 1.6TDI 5VXL	Ericssons Bildemontering AB 0370-28100	17.899 A
5577 7425	W99073 200 SEK	KIA Cee'd, Cee'd SW -16 Spolarpump Vindruta	5DR CBI 1.6 CRDI 6VXL	Ericssons Bildemontering AB 0370-28100	11.022 A
3502 7425	W45082 200 SEK	Opel Insignia -11 Spolarpump Vindruta	5DR CBI 2.0T FLEXI 6VXL	Ericssons Bildemontering AB 0370-28100	16.315 A
1529 7425	W74328 250 SEK	BMW 3-Series -07 Spolarpump Vindruta	4DR SED 330 3.0XI AUTO	Ericssons Bildemontering AB 0370-28100	19.280 A
3319 7425	W47953 300 SEK	Mercedes SLK-Class -08 Spolarpump Vindruta	2DR CAB 200 K AUTO	Ericssons Bildemontering AB 0370-28100	23.551 A
3870 7425	W98681 200 SEK	Renault Kadjar -17 Spolarpump Vindruta	5DR 1,2TCE 6VXL FWD130HK FWD	Ericssons Bildemontering AB 0370-28100	5.506 A
5073 7425	W98522 150 SEK	Volvo S60 -12 Spolarpump Vindruta	4DR SED 1,6 T3 6VXL 2WDTRIM LEVEL 2 (MOMENTUM)	Ericssons Bildemontering AB 0370-28100	14.384 A
5077 7425	W98508 150 SEK	Volvo V60 -13 Spolarpump Vindruta	5DR CBI D4 2.4 AUTO	Ericssons Bildemontering AB 0370-28100	21.575 A
5564 7425	W98463 250 SEK	KIA Rio -13 Spolarpump Vindruta	5DR CC 1,2 5VXL 2WDDOHC - MPI	Ericssons Bildemontering AB 0370-28100	12.771 A
1439 7425	W32950 200 SEK	Dacia Sandero / Sandero Stepway -16 Spolarpump Vindruta	5DR CC 1.2TCE 5VXL	Ericssons Bildemontering AB 0370-28100	8.952 A
5313 7425	W84020 150 SEK	Seat Ibiza -07 Spolarpump Vindruta	5DR CC 1.4TDI 5VXL	Ericssons Bildemontering AB 0370-28100	- A
4973 7425	W86979 150 SEK	VW Caddy -12 Spolarpump Vindruta	5DR SKÅP MAXI 2.0TDI AUTO	Ericssons Bildemontering AB 0370-28100	30.201 A
4929 7425	W34630 200 SEK	VW Passat -14 Spolarpump Vindruta	5DR CBI 2.0 TDI 6VXL 4WD	Ericssons Bildemontering AB 0370-28100	19.986 A
1445 7425	W98048 150 SEK	Dacia Lodgy -16 Spolarpump Vindruta	5DR CBI 1.5DCI 6VXL	Ericssons Bildemontering AB 0370-28100	9.384 A
3861 7425	W26074 200 SEK	Renault Megane -11 Spolarpump Vindruta	5DR CBI 1,6 16V 6VXL	Ericssons Bildemontering AB 0370-28100	13.707 A
3334 7425	W21212 200 SEK	Mercedes C-Class -11 Spolarpump Vindruta	5DR CBI C220 2.2 CDI AUTOC 220 CDI BLUEEFFICIENCY	Ericssons Bildemontering AB 0370-28100	24.127 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4973 7425	W97608 150 SEK	VW Caddy -14 Spolarpump Vindruta	5DR BUSS 2.0ECO 5VXLECOFUEL	Ericssons Bildemontering AB 0370-28100	8.024 A
2191 7425	W96194 250 SEK	Nissan NV200 / NV200 Combi -11 Spolarpump Vindruta	5DR SKÅP 1.5DCI 5VXL	Ericssons Bildemontering AB 0370-28100	10.223 A
3954 7425	W41699 300 SEK	LandRover Discovery -06 Spolarpump Vindruta	5DR SUV 2.7 TD AUTOVF HJUL SKADAD	Ericssons Bildemontering AB 0370-28100	25.345 A
4929 7425	W20605 200 SEK	VW Passat -14 Spolarpump Vindruta	5DR CBI 2.0TDI AUTO 4WD	Ericssons Bildemontering AB 0370-28100	23.411 A
3308 7425	W93856 200 SEK	Mercedes B-Class -06 Spolarpump Vindruta	5DR CC B200 AUT.B 200 SPORTS TOURER	Ericssons Bildemontering AB 0370-28100	19.568 A
4937 7425	W17008 200 SEK	VW Polo -11 Spolarpump Vindruta	5DR CC 1.4 5VXL	Ericssons Bildemontering AB 0370-28100	28.999 A