

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
5051 7445	W89908 299 SEK	Volvo 740 -90 Spak Torkar / Spolaromkoppl.	VOLVO 740VOLVO 745-882 GLT-PKT 4+6 STIFT	Ekholms Bildemontering AB 019-577088	- A
5051 7445	W75061 250 SEK	Volvo 740 -92 Spak Torkar / Spolaromkoppl.	5DCBI 2,3 GL LGRÅ KOMBI	Ekholms Bildemontering AB 019-577088	- A
5051 7445	W27576 166 SEK	Volvo 740 -88 Spak Torkar / Spolaromkoppl.	5DCBI GLE B230E 4+OD LGRÅ	Ekholms Bildemontering AB 019-577088	26.585 A
5051 7445	W62227 250 SEK	Volvo 740 -91 Spak Torkar / Spolaromkoppl.	4DSED 2,3 GL RÖD	Ekholms Bildemontering AB 019-577088	- A
5051 7445	W93166	Volvo 740 -91 Spak Torkar / Spolaromkoppl.	5D CBI GL B230F 5VX VIT FRAM+BAKRUTA	Ekholms Bildemontering AB 019-577088	26.747 A
5051 7445	W30282	Volvo 740 -90 Spak Torkar / Spolaromkoppl.	4DSED GL 5VX RÖD	Ekholms Bildemontering AB 019-577088	12.144 A
5051 7445	W60486	Volvo 740 -88 Spak Torkar / Spolaromkoppl.	5DCBI GL M46 KAT SVART	Ekholms Bildemontering AB 019-577088	23.927 A
5051 7445	W8826	Volvo 740 -90 Spak Torkar / Spolaromkoppl.	4DSED GL B230F 5VX VIT	Ekholms Bildemontering AB 019-577088	13.261 A
5051 7445	W6838	Volvo 740 -89 Spak Torkar / Spolaromkoppl.	4DSED GLT B230F 5VX RÖD	Ekholms Bildemontering AB 019-577088	10.233 A
5051 7445	W61832	Volvo 740 -90 Spak Torkar / Spolaromkoppl.	5DCBI GLTPKT 4+OD RÖD.ABS	Ekholms Bildemontering AB 019-577088	14.362 A
5051 7445	W20136	Volvo 740 -88 Spak Torkar / Spolaromkoppl.	CBI GL B230F I 5VX VIT TILL KOMBI 745	Ekholms Bildemontering AB 019-577088	11.900 A
5051 7445	W66976	Volvo 740 -88 Spak Torkar / Spolaromkoppl.	4DSED TURBO INT.4+OD LBLÅ	Ekholms Bildemontering AB 019-577088	- A