

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
1341 7445	W9591 200 SEK	Audi A3, S3 -01 Spak Torkar / Spolaromkopplare	AUDI A3 1.6 AUDI A3 1.6	Välsta Bildemontering AB 0650-743200	40.520 A
5056 7445	W16311 200 SEK	Volvo S70, V70, V70 XC -00 Spak Torkar / Spolaromkopplare Inre	V70 I 2.4 140 HK V70 I 2.4 140 HK	Välsta Bildemontering AB 0650-743200	38.333 A
5055 7445	W15186 250 SEK	Volvo 850 -96 Spak Torkar / Spolaromkopplare	850 KOMBI 2.4850 KOMBI 2.4	Välsta Bildemontering AB 0650-743200	50.424 A
5061 7445	W6960 200 SEK	Volvo V70 -01 Spak Torkar / Spolaromkopplare	V70 II 2.4 T V70 II 2.4 T UTAN REGSENSOR	Välsta Bildemontering AB 0650-743200	30.365 A
5290 7445	W5746 200 SEK	Hyundai i30 -08 Spak Torkar / Spolaromkopplare	I30 KOMBI 2.0 CRDI I30 KOMBI 2.0 CRDI	Välsta Bildemontering AB 0650-743200	175.569 A
3210 7445	W14500 250 SEK	Mazda 6 -07 Spak Torkar / Spolaromkopplare	6 HATCHBACK 2.06 HATCHBACK 2.0	Välsta Bildemontering AB 0650-743200	26.060 A
5063 7445	W1365 300 SEK	Volvo V70 -11 Spak Torkar / Spolaromkopplare	V70 III D5 AWD V70 III D5 AWD MED REGSENSOR	Välsta Bildemontering AB 0650-743200	24.540 A
5024 7445	W8346 200 SEK	Volvo V50 -04 Spak Torkar / Spolaromkopplare Höger	V50 2.0 DV50 2.0 D	Välsta Bildemontering AB 0650-743200	47.783 A
5062 7445	W11607 200 SEK	Volvo V70 -07 Spak Torkar / Spolaromkopplare Höger	V70 II 2.4 170 HK V70 II 2.4 170 HK	Välsta Bildemontering AB 0650-743200	27.724 A
3847 7445	W14753 250 SEK	Renault Scenic, Grand Scenic -01 Spak Torkar / Spolaromkopplare	MEGANE SCENIC 1.6 16V MEGANE SCENIC 1.6 16V	Välsta Bildemontering AB 0650-743200	17.613 A
5237 7445	W12173 300 SEK	Hyundai Tucson -04 Spak Torkar / Spolaromkopplare	HYUNDAI TUCSON 2.7HYUNDAI TUCSON 2.7	Välsta Bildemontering AB 0650-743200	33.103 A
5285 7445	W3535 300 SEK	Hyundai i20 -10 Spak Torkar / Spolaromkopplare	HYUNDAI I20 1.2HYUNDAI I20 1.2	Välsta Bildemontering AB 0650-743200	13.203 A
4573 7445	W2111 250 SEK	Toyota Avensis -03 Spak Torkar / Spolaromkopplare	AVENSIS KOMBI 1.8AVENSIS KOMBI 1.8	Välsta Bildemontering AB 0650-743200	26.742 A
2190 7445	W1664 300 SEK	Nissan Terrano -98 Spak Torkar / Spolaromkopplare	TERRANO II 2.4 4WDTERRANO II 2.4 4WD	Välsta Bildemontering AB 0650-743200	29.098 A
5203 7445	W4383 400 SEK	Hyundai Getz -04 Spak Torkar / Spolaromkopplare	HYUNDAI GETZ 1.6	Välsta Bildemontering AB 0650-743200	15.376 A
5060 7445	W12621 150 SEK	Volvo 940 -97 Spak Torkar / Spolaromkopplare	940 II KOMBI 2.3 B230FK 940 II KOMBI 2.3 B230FK	Välsta Bildemontering AB 0650-743200	45.485 A
5063 7445	W10692 300 SEK	Volvo V70 -07 Spak Torkar / Spolaromkopplare	V70 III D5V70 III D5 FÖR REGSENSOR	Välsta Bildemontering AB 0650-743200	32.111 A
5063 7445	W5537 250 SEK	Volvo V70 -08 Spak Torkar / Spolaromkopplare	V70 III 2.4 DV70 III 2.4 D	Välsta Bildemontering AB 0650-743200	31.730 A
5061 7445	W6456 200 SEK	Volvo V70 -01 Spak Torkar / Spolaromkopplare	VOLVO V70 II 2.4 170 HKVOLVO V70 II 2.4 170 HK	Välsta Bildemontering AB 0650-743200	23.430 A
5082 7445	W5692 200 SEK	Volvo XC70 -05 Spak Torkar / Spolaromkopplare	VOLVO XC70 CROSS COUNTRY 2.5 T XC AW	Välsta Bildemontering AB 0650-743200	32.255 A
5063 7445	W12234 250 SEK	Volvo V70 -08 Spak Torkar / Spolaromkopplare	V70 III 2.0 DV70 III 2.0 D	Välsta Bildemontering AB 0650-743200	19.219 A
5061 7445	W13665 200 SEK	Volvo V70 -01 Spak Torkar / Spolaromkopplare	V70 II 2.4 140 HKV70 II 2.4 140 HK	Välsta Bildemontering AB 0650-743200	27.730 A
5063 7445	W18696 250 SEK	Volvo V70 -08 Spak Torkar / Spolaromkopplare	V70 III 2.0 FLEXIFUEL	Välsta Bildemontering AB 0650-743200	9.841 A
4976 7445	W2251 350 SEK	VW Caddy -07 Spak Torkar / Spolaromkopplare	CADDY III SKÅP 1.9 TDICADDY III SKÅP 1.9 TDI	Välsta Bildemontering AB 0650-743200	23.868 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
5071 7445	W12219 250 SEK	Volvo S60 -03 Spak Torkar / Spolaromkopplare	S60 I 2.4 D5 163 HKS60 I 2.4 D5 163 HK SEDAN	Välsta Bildemontering AB 0650-743200	37.448 A
4914 7445	W15717 350 SEK	VW Golf, e-Golf -07 Spak Torkar / Spolaromkopplare Inre	GOLF V 1.6GOLF V 1.6 INRE	Välsta Bildemontering AB 0650-743200	9.529 A
4085 7445	W19316 100 SEK	Saab 9000 -96 Spak Torkar / Spolaromkopplare	9000 HALVKOMBI 2.0 -16 CS9000 HALVKOMBI 2.0 -16 CS	Välsta Bildemontering AB 0650-743200	35.242 A
5061 7445	W8261 200 SEK	Volvo V70 -00 Spak Torkar / Spolaromkopplare Inre Fram	V70 II 2.4 TV70 II 2.4 T INV FRAM	Välsta Bildemontering AB 0650-743200	29.166 A
3448 7445	W11812 400 SEK	Mitsubishi Outlander -12 Spak Torkar / Spolaromkopplare Inre Fram	OUTLANDER II 2.2 DI-D 4WDOUTLANDER II 2.2 DI-D 4WD INV FRAM	Välsta Bildemontering AB 0650-743200	16.358 A
4572 7445	W6687 120 SEK	Toyota Avensis -99 Spak Torkar / Spolaromkopplare Inre Fram	TOYOTA AVENSIS LIFTBACK 1TOYOTA AVENSIS LIFTBACK 1 INV RAM	Välsta Bildemontering AB 0650-743200	28.493 A