

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4490 7268	W614813 500 SEK	Toyota RAV 4 -20 Knacksensor	RAV4 19-8gt;A25A-FXS V 5DR STATIONSVAGN KOMBIVAGN E	Lycksele Bildemontering AB 0950-12140	12.720 A
1733 7268	W614492 325 SEK	Citroen C5 -22 Knacksensor	C5 AIRCROSS HNS AUTOMAT 5DR SUV BENSIN	Lycksele Bildemontering AB 0950-12140	320 A
4223 7268	W613663 562 SEK	Skoda Kamiq -21 Knacksensor Vänster Fram	KAMIQ DLAA AUTOMAT 5DR HALVKOMBI BENSIN VÄNSTER FRAM	Lycksele Bildemontering AB 0950-12140	4.122 A
3232 7268	W612781 625 SEK	Mazda CX-60 -22 Knacksensor	CX-60 AUTOMAT 5DR SUV ELHYBRID BENSIN	Lycksele Bildemontering AB 0950-12140	1.844 A
2451 7268	W611104 400 SEK	Ford Mondeo -21 Knacksensor	MONDEO UACC V 5DR STATIONSVAGN KOMBIVAGN ELHYBRID	Lycksele Bildemontering AB 0950-12140	9.623 A
2451 7268	W611103 400 SEK	Ford Mondeo -21 Knacksensor	MONDEO UACC V 5DR STATIONSVAGN KOMBIVAGN ELHYBRID	Lycksele Bildemontering AB 0950-12140	9.623 A
5292 7268	W607249 500 SEK	Hyundai i30 -20 Knacksensor	I 30 G4LD AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	2.407 A
4489 7268	W606778 625 SEK	Toyota Corolla -23 Knacksensor	COROLLA 1,8	Lycksele Bildemontering AB 0950-12140	189 A
4957 7268	W605130 625 SEK	VW Golf, e-Golf -23 Knacksensor	VOLKSWAGEN, VW DPBA AUTOMAT 5DR STATIONSVAGN KOMBI	Lycksele Bildemontering AB 0950-12140	1.231 A
4673 7268	W601243 500 SEK	Toyota Yaris Cross -22 Knacksensor	YARIS CROSS M15A-FXE V 5DR CROSS-OVER ELHYBRID BEN	Lycksele Bildemontering AB 0950-12140	1.830 A
8701 7268	W600179 350 SEK	Ski-Doo Snöskoter -15 Knacksensor	SUMMIT X 154" 800ETEC	Lycksele Bildemontering AB 0950-12140	499 A
4719 7268	W597830 175 SEK	Mini Cooper Clubman F54 -19 Knacksensor	COOPER CLUBMAN B48-A20A AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	4.004 A
4719 7268	W597831 175 SEK	Mini Cooper Clubman F54 -19 Knacksensor	COOPER CLUBMAN B48-A20A AUTOMAT 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	4.004 A
8702 7268	W596821 400 SEK	Lynx Snöskoter -18 Knacksensor	BOOND DS3900 850 E-TEC RADIEN 850ETEC	Lycksele Bildemontering AB 0950-12140	963 A
5287 7268	W596439 438 SEK	Hyundai i20 -22 Knacksensor	I20 G3LE AUTOMAT 5DR KOMBI-SEDAN BENSIN	Lycksele Bildemontering AB 0950-12140	900 A
8703 7268	W595410 400 SEK	Arctic Cat Snöskoter -19 Knacksensor	ASCENDER M6000	Lycksele Bildemontering AB 0950-12140	435 A
8705 7268	W593753 500 SEK	Polaris Snöskoter -16 Knacksensor	800 PRO RMK 163 AXYS 800CFI	Lycksele Bildemontering AB 0950-12140	160 A
2455 7268	W592845 162 SEK	Ford Kuga -23 Knacksensor	KUGA BGDC V 5DR SUV ELHYBRID BENSIN	Lycksele Bildemontering AB 0950-12140	382 A
5573 7268	W590746 125 SEK	KIA Sorento -21 Knacksensor	SORENTO G4FT AUTOMAT 5DR SUV ELHYBRID BENSIN	Lycksele Bildemontering AB 0950-12140	7.024 A
3335 7268	W578085 200 SEK	Mercedes C-Class -15 Knacksensor	C 180 M274.910 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	8.352 A
5576 7268	W577942 400 SEK	KIA Cee'd, Cee'd SW -23 Knacksensor	CEED G4LE AUTOMAT 5DR KOMBI ELHYBRID BENSIN	Lycksele Bildemontering AB 0950-12140	148 A
8702 7268	W577395 400 SEK	Lynx Snöskoter -11 Knacksensor	COM. LTD 600 E-TEC XU 600ETEC	Lycksele Bildemontering AB 0950-12140	904 A
1347 7268	W573627 562 SEK	Audi A3, S3 -21 Knacksensor	A3 SPORTBACK DPCA MANUELL 5DR KOMBI BENSIN	Lycksele Bildemontering AB 0950-12140	1.390 A
8705 7268	W563729 500 SEK	Polaris Snöskoter -17 Knacksensor	800 PRO R AXYS 800CFI BOSCH	Lycksele Bildemontering AB 0950-12140	260 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
1353 7268	W553988 600 SEK	Audi A1 / S1 -19 Knacksensor	A1 SPORTBACK DKRF AUTOMAT 5DR KOMBI-SEDAN BENSIN VEVAXEL	Lycksele Bildmontering AB 0950-12140	5.157 A
5576 7268	W543730 625 SEK	KIA Cee'd, Cee'd SW -20 Knacksensor	CEED GT-LINE GALE AUTOMAT 4DR KOMBI ELHYBRID BENSIN	Lycksele Bildmontering AB 0950-12140	1.482 A
8701 7268	W541906 350 SEK	Ski-Doo Snöskoter -09 Knacksensor	RENEGADE X 600 E 600ETEC	Lycksele Bildmontering AB 0950-12140	778 A
8702 7268	W528293 400 SEK	Lynx Snöskoter -16 Knacksensor	49 RANGER 600 E-TEC 600ETEC	Lycksele Bildmontering AB 0950-12140	1.065 A
8706 7268	W527302 625 SEK	Yamaha Snöskoter -21 Knacksensor	MOUNTAINMAX MOUNTAIN MAX 800	Lycksele Bildmontering AB 0950-12140	52 A
8705 7268	W512795 500 SEK	Polaris Snöskoter -16 Knacksensor	SKS 800 155" 800CF12 800CF12	Lycksele Bildmontering AB 0950-12140	396 A