

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4972 5025	W696819 300 SEK	VW Caddy -20 Parkeringshjälp Backsensor	1.4 TSI CNG MINIFLEX 110HK 1.4/CPWA 6VXL 5DR SKP BI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	585 A
3626 5025	W554956	Peugeot 3008 -18 Parkeringshjälp Backsensor	1.6HDI DIESEL CROSSOVER 120HK 1.6HDI/BHZ AUTOMAT HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	962 A
3626 5025	W554957	Peugeot 3008 -18 Parkeringshjälp Backsensor	1.6HDI DIESEL CROSSOVER 120HK 1.6HDI/BHZ AUTOMAT HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	962 A
3626 5025	W554959	Peugeot 3008 -18 Parkeringshjälp Backsensor	1.6HDI DIESEL CROSSOVER 120HK 1.6HDI/BHZ AUTOMAT HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	962 A
3626 5025	W554958	Peugeot 3008 -18 Parkeringshjälp Backsensor	1.6HDI DIESEL CROSSOVER 120HK 1.6HDI/BHZ AUTOMAT HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	962 A
1707 5025	W451283 300 SEK	Citroen Berlingo -15 Parkeringshjälp Backsensor	1.6HDI 90HK 1.6HDI/9HF 5VXL 5DR SKP DIESEL TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	1.045 A
5260 5025	W637743	Hyundai Nexso -19 Parkeringshjälp Backsensor	FCEV FUELCEL/VÄTGAS FM12 AUTOMAT HGV HYDROGEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.251 A
5260 5025	W637742	Hyundai Nexso -19 Parkeringshjälp Backsensor	FCEV FUELCEL/VÄTGAS FM12 AUTOMAT HGV HYDROGEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.251 A
5260 5025	W637744	Hyundai Nexso -19 Parkeringshjälp Backsensor	FCEV FUELCEL/VÄTGAS FM12 AUTOMAT HGV HYDROGEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.251 A
5260 5025	W637741	Hyundai Nexso -19 Parkeringshjälp Backsensor	FCEV FUELCEL/VÄTGAS FM12 AUTOMAT HGV HYDROGEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.251 A
5260 5025	W637745	Hyundai Nexso -19 Parkeringshjälp Backsensor	FCEV FUELCEL/VÄTGAS FM12 AUTOMAT HGV HYDROGEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.251 A
3821 5025	W621873	Renault Zoe -18 Parkeringshjälp Backsensor	EV ZE40 CC 109HK 40KW 5AQ80 AUTOMAT 5DR CC EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.376 A
3821 5025	W621870	Renault Zoe -18 Parkeringshjälp Backsensor	EV ZE40 CC 109HK 40KW 5AQ80 AUTOMAT 5DR CC EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.376 A
3821 5025	W621871	Renault Zoe -18 Parkeringshjälp Backsensor	EV ZE40 CC 109HK 40KW 5AQ80 AUTOMAT 5DR CC EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.376 A
3821 5025	W621872	Renault Zoe -18 Parkeringshjälp Backsensor	EV ZE40 CC 109HK 40KW 5AQ80 AUTOMAT 5DR CC EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.376 A
3529 5025	W709434 150 SEK	Opel Astra -19 Parkeringshjälp Backsensor	1.6 CDTI KOMBI-SEDAN 110HK 1.6/B16DTE 6VXL 5DR CSE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.400 A
3529 5025	W709436 150 SEK	Opel Astra -19 Parkeringshjälp Backsensor	1.6 CDTI KOMBI-SEDAN 110HK 1.6/B16DTE 6VXL 5DR CSE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.400 A
3529 5025	W709435 150 SEK	Opel Astra -19 Parkeringshjälp Backsensor	1.6 CDTI KOMBI-SEDAN 110HK 1.6/B16DTE 6VXL 5DR CSE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.400 A
3529 5025	W709437 150 SEK	Opel Astra -19 Parkeringshjälp Backsensor	1.6 CDTI KOMBI-SEDAN 110HK 1.6/B16DTE 6VXL 5DR CSE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.400 A
4250 5025	W537369 300 SEK	Tesla Model S -15 Parkeringshjälp Backsensor	P85D P85D 5DR SED EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.425 A
4250 5025	W537367 300 SEK	Tesla Model S -15 Parkeringshjälp Backsensor	P85D P85D 5DR SED EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.425 A
4250 5025	W537370 300 SEK	Tesla Model S -15 Parkeringshjälp Backsensor	P85D P85D 5DR SED EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.425 A
4250 5025	W537368 300 SEK	Tesla Model S -15 Parkeringshjälp Backsensor	P85D P85D 5DR SED EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.425 A
4250 5025	W537366 300 SEK	Tesla Model S -15 Parkeringshjälp Backsensor	P85D P85D 5DR SED EL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.425 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
1549 5025	W648387 700 SEK	BMW X6 -21 Parkeringshjälp Backsensor	4.4T SUV 530HK 4.4iN63B44D AUTOMAT 5DR SUV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.438 A
1549 5025	W648386 700 SEK	BMW X6 -21 Parkeringshjälp Backsensor	4.4T SUV 530HK 4.4iN63B44D AUTOMAT 5DR SUV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.438 A
3632 5025	W565085 250 SEK	Peugeot 308 -18 Parkeringshjälp Backsensor	1.2THP SW KOMBI 110HK 1.2THP/HNZ 5VXL 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.462 A
3632 5025	W565087 250 SEK	Peugeot 308 -18 Parkeringshjälp Backsensor	1.2THP SW KOMBI 110HK 1.2THP/HNZ 5VXL 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.462 A
3632 5025	W565088 250 SEK	Peugeot 308 -18 Parkeringshjälp Backsensor	1.2THP SW KOMBI 110HK 1.2THP/HNZ 5VXL 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.462 A
3632 5025	W565086 250 SEK	Peugeot 308 -18 Parkeringshjälp Backsensor	1.2THP SW KOMBI 110HK 1.2THP/HNZ 5VXL 5DR HGV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	1.462 A