

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
3502 7840	W36628 300 SEK	Opel Insignia -16 Vindrute torkararm / armar	5DR CBI 1,6D 6VXLPAKETKOD IXI3 13227398	Ericssons Bildemontering AB 0370-28100	5.762 A
5063 7840	W33601 300 SEK	Volvo V70 -10 Vindrute torkararm / armar	5DR CBI 2.4 D5 AUTO 31276002	Ericssons Bildemontering AB 0370-28100	31.122 A
5083 7840	W25306 300 SEK	Volvo XC70 -10 Vindrute torkararm / armar	5DR CBI 2.4 D5 AUTO 31276002	Ericssons Bildemontering AB 0370-28100	32.476 A
1529 7840	W9589 300 SEK	BMW 3-Series -07 Vindrute torkararm / armar	4DR SED 2.0D 5VXL 61 61 9 449 916	Ericssons Bildemontering AB 0370-28100	23.919 A
1323 7840	W23494 300 SEK	Audi A4, S4 -13 Vindrute torkararm / armar	5DR CBI 2.0TDI AUTO 8K1 955 407	Ericssons Bildemontering AB 0370-28100	17.285 A
3646 7840	W11333 300 SEK	Peugeot 508 -12 Vindrute torkararm / armar	5DR CBI 1.6HDI 5VXL 9686437680	Ericssons Bildemontering AB 0370-28100	10.015 A
3621 7840	W6611 300 SEK	Peugeot 208 -17 Vindrute torkararm / armar	5DR CC 1.2VTI 5VXL 16 083 931 80	Ericssons Bildemontering AB 0370-28100	3.569 A
5024 7840	W46023 300 SEK	Volvo V50 -07 Vindrute torkararm / armar	5DR CBI 2.4 AUT 30699609	Ericssons Bildemontering AB 0370-28100	24.631 A
2719 7840	W53482 300 SEK	Honda Civic -12 Vindrute torkararm / armar	5DR CC 1.8 6VXL 76600TV0G01	Ericssons Bildemontering AB 0370-28100	17.300 A
1446 7840	W39802 200 SEK	Dacia Dokker -18 Vindrute torkararm / armar	5DR BUS 1.2 5VXL 288817245R	Ericssons Bildemontering AB 0370-28100	- A
4908 7840	W29595 300 SEK	VW Golf, e-Golf -10 Vindrute torkararm / armar	5DR CC 1.6TDI 5VXL 1Q1 955 410	Ericssons Bildemontering AB 0370-28100	16.706 A
1529 7840	W24903 300 SEK	BMW 3-Series -07 Vindrute torkararm / armar	5DR CBI 325D AUT145KW 61 61 9 449 916	Ericssons Bildemontering AB 0370-28100	25.492 A
5024 7840	W14321 300 SEK	Volvo V50 -08 Vindrute torkararm / armar	5DR CBI 1.8 30699609	Ericssons Bildemontering AB 0370-28100	27.513 A
3592 7840	W51975 300 SEK	Opel Vivaro -11 Vindrute torkararm / armar	5DR SKÅP 2.0 6VXL 91160060	Ericssons Bildemontering AB 0370-28100	16.306 A
4544 7840	W93223 300 SEK	Toyota Verso -09 Vindrute torkararm / armar	5DR CBI 1.8 16V 6VXL 852210F030	Ericssons Bildemontering AB 0370-28100	18.451 A
2433 7840	W93046 400 SEK	Ford C-MAX, Ford Focus C-MAX -11 Vindrute torkararm / armar	5DR CBI 1.6HDI 6VXL 1899697	Ericssons Bildemontering AB 0370-28100	- A
4908 7840	W92642 300 SEK	VW Golf, e-Golf -11 Vindrute torkararm / armar	5DR CC 1.6 5VXL 1Q1 955 410	Ericssons Bildemontering AB 0370-28100	18.186 A
5064 7840	W92474 300 SEK	Volvo V70 -16 Vindrute torkararm / armar	5DR CBI 2.0MK3 AUT. 31276002	Ericssons Bildemontering AB 0370-28100	39.800 A
3691 7840	W92345 200 SEK	Peugeot Partner -18 Vindrute torkararm / armar	5DR SKÅP 1.6HDI 5VXL 6429 FG	Ericssons Bildemontering AB 0370-28100	13.518 A
1516 7840	W12607 300 SEK	BMW X1 -10 Vindrute torkararm / armar	5DR SUV 2,0D 4WD 6VXLFELMEDELANDE ANTISSPIN 61 61 9 450 000	Ericssons Bildemontering AB 0370-28100	32.831 A
5577 7840	W91611 300 SEK	KIA Cee'd, Cee'd SW -13 Vindrute torkararm / armar	5DR CBI 1.6 CRDI 6VXL 98310A2000	Ericssons Bildemontering AB 0370-28100	16.261 A
3632 7840	W39395 300 SEK	Peugeot 308 -17 Vindrute torkararm / armar	5DR CBI 1.6HDI AUTO	Ericssons Bildemontering AB 0370-28100	6.125 A
5024 7840	W62616 300 SEK	Volvo V50 -07 Vindrute torkararm / armar	5DR CBI 1.8FLEX 5VXL 30699609	Ericssons Bildemontering AB 0370-28100	21.656 A
4972 7840	W91723 300 SEK	VW Caddy -18 Vindrute torkararm / armar	2DR SKÅP 2,0D AUT 6VX 2K1955409C	Ericssons Bildemontering AB 0370-28100	10.581 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
5313 7840	W77368 200 SEK	Seat Ibiza -07 Vindrute torkarm / armar	5DR CC 1.4TDI 5VXL 6L1 955 409 E	Ericssons Bildemontering AB 0370-28100	21.055 A
2790 7840	W35769 300 SEK	Honda CR-V -07 Vindrute torkarm / armar	5DR SUV 2.0 16V VTEC AUTO	Ericssons Bildemontering AB 0370-28100	14.647 A
3955 7840	W36802 300 SEK	LandRover Range Rover -07 Vindrute torkarm / armar	5DR SUV 2,7 V6 AUTL320 RANGE ROVER SPORT 6H323405BA	Ericssons Bildemontering AB 0370-28100	14.810 A
5069 7840	W86789 300 SEK	Volvo S40 04-12 -06 Vindrute torkarm / armar	4DR SED 2.4 5VXL 30699609	Ericssons Bildemontering AB 0370-28100	32.505 A
4411 7840	W90999 300 SEK	Suzuki SX4 S-Cross -15 Vindrute torkarm / armar	5DR CC 1.6L 5VXL AWD SX4 38330-61M00	Ericssons Bildemontering AB 0370-28100	8.085 A
5063 7840	W90473 150 SEK	Volvo V70 -12 Vindrute torkarm / armar	5DR CBI 1.6D D2 6VXL ENDAST HÖ	Ericssons Bildemontering AB 0370-28100	31.820 A