

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
3616 7646	W70621 250 SEK	Peugeot 206 -07 ABS Sensor	FRAM	Ericssons Bildemontering AB 0370-28100	- A
5079 7646	W28549 350 SEK	Volvo V60 Cross Country -16 ABS Sensor	5DR CBI 2.0 D3 CROS AUTO BAK	Ericssons Bildemontering AB 0370-28100	16.092 A
5075 7646	W22015 200 SEK	Volvo XC60 -09 ABS Sensor	5DR SUV 2.4 D MK1 6VXL	Ericssons Bildemontering AB 0370-28100	33.691 A
5075 7646	W20072 200 SEK	Volvo XC60 -09 ABS Sensor	5DR SUV 2.4 D MK1 6VXL	Ericssons Bildemontering AB 0370-28100	33.691 A
5072 7646	W34353 200 SEK	Volvo S60 -05 ABS Sensor	4DR SED 2.4 5VXL VB	Ericssons Bildemontering AB 0370-28100	29.312 A
5072 7646	W34212 200 SEK	Volvo S60 -05 ABS Sensor	4DR SED 2.4 5VXL HB	Ericssons Bildemontering AB 0370-28100	29.312 A
5075 7646	W76320 300 SEK	Volvo XC60 -09 ABS Sensor	5DR SUV 2.4D5 6VXL BAK	Ericssons Bildemontering AB 0370-28100	26.153 A
5075 7646	W76243 300 SEK	Volvo XC60 -09 ABS Sensor	5DR SUV 2.4D5 6VXL BAK	Ericssons Bildemontering AB 0370-28100	26.153 A
4553 7646	W21104 250 SEK	Toyota Corolla -06 ABS Sensor	5DR CBI 1.6 5VXL VF	Ericssons Bildemontering AB 0370-28100	28.777 A
3210 7646	W90554 200 SEK	Mazda 6 -06 ABS Sensor	5DR CBI 2.0 6VXL VB	Ericssons Bildemontering AB 0370-28100	16.904 A
3616 7646	W90262 300 SEK	Peugeot 206 -06 ABS Sensor	5DR CC 1.4 5VXL BAK	Ericssons Bildemontering AB 0370-28100	20.723 A
3898 7646	W87159 300 SEK	Renault Master -02 ABS Sensor	5DR SKÅP 2.5DCI 5VXLSAKNAS STYRENHET BAK	Ericssons Bildemontering AB 0370-28100	14.639 A
4572 7646	W82370 200 SEK	Toyota Avensis -00 ABS Sensor	5DR CBI 1,8 VVT-I 5VXL VF	Ericssons Bildemontering AB 0370-28100	14.590 A
5061 7646	W69312 250 SEK	Volvo V70 -03 ABS Sensor	5DR CBI VB	Ericssons Bildemontering AB 0370-28100	41.410 A
5061 7646	W68824 250 SEK	Volvo V70 -03 ABS Sensor	5DR CBI HB	Ericssons Bildemontering AB 0370-28100	41.410 A
1318 7646	W15477 250 SEK	Audi A4, S4 -01 ABS Sensor	4DR SED 1,9TDI 5VXL HF	Ericssons Bildemontering AB 0370-28100	25.417 A
1318 7646	W15503 250 SEK	Audi A4, S4 -01 ABS Sensor	4DR SED 1,9TDI 5VXL VF	Ericssons Bildemontering AB 0370-28100	25.417 A
5071 7646	W12541 150 SEK	Volvo S60 -04 ABS Sensor	4DR SED 2.4 5VXLGENERATOR KASS VB	Ericssons Bildemontering AB 0370-28100	19.570 A
5071 7646	W12309 150 SEK	Volvo S60 -04 ABS Sensor	4DR SED 2.4 5VXLGENERATOR KASS HB	Ericssons Bildemontering AB 0370-28100	19.570 A
5061 7646	W21312 250 SEK	Volvo V70 -00 ABS Sensor	5DR CBI VB	Ericssons Bildemontering AB 0370-28100	28.486 A
5061 7646	W21253 250 SEK	Volvo V70 -00 ABS Sensor	5DR CBI HB	Ericssons Bildemontering AB 0370-28100	28.486 A
5071 7646	W68699 150 SEK	Volvo S60 -01 ABS Sensor	4DR SED 2.4T AUTO	Ericssons Bildemontering AB 0370-28100	31.307 A
5071 7646	W68300 150 SEK	Volvo S60 -01 ABS Sensor	4DR SED 2.4T AUTO	Ericssons Bildemontering AB 0370-28100	31.307 A
3570 7646	W80406 150 SEK	Opel Meriva -10 ABS Sensor	5DR CBI 1.6 16V 5VXL VF	Ericssons Bildemontering AB 0370-28100	13.898 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
3570 7646	W80405 150 SEK	Opel Meriva -10 ABS Sensor	5DR CBI 1.6 16V 5VXL HF	Ericssons Bildemontering AB 0370-28100	13.898 A
3210 7646	W78689 250 SEK	Mazda 6 -06 ABS Sensor	5DRCBI 2,0 16V 6VXL VB	Ericssons Bildemontering AB 0370-28100	13.253 A
3210 7646	W78688 250 SEK	Mazda 6 -06 ABS Sensor	5DRCBI 2,0 16V 6VXL HB	Ericssons Bildemontering AB 0370-28100	13.253 A
3631 7646	W73489 150 SEK	Peugeot 308 -13 ABS Sensor	5DR CBI 1.6 5VXL VF	Ericssons Bildemontering AB 0370-28100	4.354 A
5061 7646	W70197 250 SEK	Volvo V70 -04 ABS Sensor	5DR CBI 2.4 5VXL VB	Ericssons Bildemontering AB 0370-28100	289.278 A
5061 7646	W70196 250 SEK	Volvo V70 -04 ABS Sensor	5DR CBI 2.4 5VXL HB	Ericssons Bildemontering AB 0370-28100	289.278 A