

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4543 3023	W61805 1.000 SEK	Toyota iQ -10 Fönsterhissmekanism	3DR CC 1.0 VVT-I 5VXL69 HK VF	Ericssons Bildemontering AB 0370-28100	13.862 A
5067 3023	W1217 500 SEK	Volvo XC90 -06 Fönsterhissmekanism	5DR SUV 2.5 TURBO AUTO HB	Ericssons Bildemontering AB 0370-28100	27.879 A
3689 3023	W98640 800 SEK	Peugeot Partner -13 Fönsterhissmekanism	5DR SKÅP 1.6HDI AUTO HF MED MOTOR	Ericssons Bildemontering AB 0370-28100	16.559 A
1528 3023	W20968 600 SEK	BMW 3-Series -02 Fönsterhissmekanism	3DR COUPE 320 24V 5VXL VF MED MOTOR	Ericssons Bildemontering AB 0370-28100	25.594 A
1707 3023	W22534 600 SEK	Citroen Berlingo -18 Fönsterhissmekanism	5DR SKÅP 1,6HDI 5VXL HF	Ericssons Bildemontering AB 0370-28100	13.544 A
2202 3023	W57383 600 SEK	Fiat 500 -12 Fönsterhissmekanism	3DR CC 1.2MPI 5VXL VF	Ericssons Bildemontering AB 0370-28100	11.570 A
2202 3023	W72147 600 SEK	Fiat 500 -12 Fönsterhissmekanism	3DR CC 1.2MPI 5VXL HF	Ericssons Bildemontering AB 0370-28100	11.570 A
2450 3023	W99305 500 SEK	Ford Mondeo -13 Fönsterhissmekanism	5DR SED 2.0 TDCI 6VXL VF	Ericssons Bildemontering AB 0370-28100	31.788 A
1520 3023	W99301 450 SEK	BMW 1-Series -09 Fönsterhissmekanism	5DR CBI 118D MK2 6VXL VF	Ericssons Bildemontering AB 0370-28100	19.200 A
5564 3023	W99296 350 SEK	KIA Rio -13 Fönsterhissmekanism	5DR CC 1,2 5VXL 2WDDOHC - MPI HF	Ericssons Bildemontering AB 0370-28100	12.771 A
2450 3023	W99286 500 SEK	Ford Mondeo -13 Fönsterhissmekanism	5DR SED 2.0 TDCI 6VXL HF	Ericssons Bildemontering AB 0370-28100	31.788 A
4303 3023	W99177 500 SEK	Subaru Outback -14 Fönsterhissmekanism	5DR CBI 2.0D AUTO VF	Ericssons Bildemontering AB 0370-28100	22.220 A
4908 3023	W99161 450 SEK	VW Golf, e-Golf -12 Fönsterhissmekanism	5DR CBI 1.6TDI AUTO VF	Ericssons Bildemontering AB 0370-28100	19.520 A
1732 3023	W99216 700 SEK	Citroen C4 -13 Fönsterhissmekanism	5DR CC 1.6VVTI 5VXL VB	Ericssons Bildemontering AB 0370-28100	4.800 A
1732 3023	W99205 700 SEK	Citroen C4 -13 Fönsterhissmekanism	5DR CC 1.6VVTI 5VXL VF	Ericssons Bildemontering AB 0370-28100	4.800 A
4929 3023	W99200 600 SEK	VW Passat -11 Fönsterhissmekanism	5DR CBI 2.0TDI HB	Ericssons Bildemontering AB 0370-28100	20.369 A
2594 3023	W99190 500 SEK	Chevrolet Cruze -10 Fönsterhissmekanism	4DR SED 1.8 5VXL HF	Ericssons Bildemontering AB 0370-28100	17.131 A
3334 3023	W99184 400 SEK	Mercedes C-Class -11 Fönsterhissmekanism	5DR CBI C220 2.2 CDI AUTOC 220 CDI BLUEEFFICIENCY HB	Ericssons Bildemontering AB 0370-28100	24.127 A
2473 3023	W99277 500 SEK	Ford Focus -12 Fönsterhissmekanism	5DR CBI 2.0 TDCI AUTO VB	Ericssons Bildemontering AB 0370-28100	29.059 A
2473 3023	W99272 500 SEK	Ford Focus -12 Fönsterhissmekanism	5DR CBI 2.0 TDCI AUTO HF	Ericssons Bildemontering AB 0370-28100	29.059 A
3502 3023	W99267 500 SEK	Opel Insignia -11 Fönsterhissmekanism	5DR CBI 2.0T FLEXI 6VXL HB	Ericssons Bildemontering AB 0370-28100	16.315 A
5290 3023	W99257 500 SEK	Hyundai i30 -09 Fönsterhissmekanism	5DR CBI 1.6CRDI AUTO HB	Ericssons Bildemontering AB 0370-28100	15.357 A
5290 3023	W99252 500 SEK	Hyundai i30 -09 Fönsterhissmekanism	5DR CBI 1.6CRDI AUTO HF	Ericssons Bildemontering AB 0370-28100	15.357 A
3334 3023	W99232 400 SEK	Mercedes C-Class -11 Fönsterhissmekanism	5DR CBI C220 2.2 CDI AUTOC 220 CDI BLUEEFFICIENCY VB	Ericssons Bildemontering AB 0370-28100	24.127 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
3343 3023	W99166 450 SEK	Mercedes E-Class 96->> -11 Fönsterhissmekanism	5DR CBI 2.2CDI AUTO VF	Ericssons Bildemontering AB 0370-28100	17.710 A
4929 3023	W99291 600 SEK	VW Passat -14 Fönsterhissmekanism	5DR CBI 2.0TDI AUTO 4WD HF	Ericssons Bildemontering AB 0370-28100	23.411 A
4687 3023	W99151 400 SEK	Toyota Urban Cruiser -10 Fönsterhissmekanism	5DR SUV 1.4D TURBO 6VXLD-4D HB	Ericssons Bildemontering AB 0370-28100	11.884 A
5025 3023	W99156 350 SEK	Volvo V50 -11 Fönsterhissmekanism	5DR CBI D2 1.6 MK2 HB	Ericssons Bildemontering AB 0370-28100	12.218 A
3502 3023	W99140 500 SEK	Opel Insignia -11 Fönsterhissmekanism	5DR CBI 2.0T FLEXI 6VXL VB	Ericssons Bildemontering AB 0370-28100	16.315 A
3954 3023	W99321 1.000 SEK	LandRover Discovery -06 Fönsterhissmekanism	5DR SUV 2.7 TD AUTOVF HJUL SKADAD HF	Ericssons Bildemontering AB 0370-28100	25.345 A