

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4984 7841	W36865 600 SEK	VW Tiguan -08 Vindrute torkarmekanism	5DR SUV 2.0 6VXL 4WD MED MOTOR	Ericssons Bildemontering AB 0370-28100	26.542 A
5063 7841	W79515 450 SEK	Volvo V70 -12 Vindrute torkarmekanism	5DR CBI 1.6 D2 6VXL31329884 STYRVÅXEL	Ericssons Bildemontering AB 0370-28100	19.249 A
3883 7841	W55260 400 SEK	Renault Kangoo -11 Vindrute torkarmekanism	35DR SKÅP 1.5DCI 5VXL	Ericssons Bildemontering AB 0370-28100	17.561 A
4208 7841	W7936 400 SEK	Skoda Octavia -08 Vindrute torkarmekanism	5DR CBI 1.6 5VXL	Ericssons Bildemontering AB 0370-28100	18.559 A
1322 7841	W99793 600 SEK	Audi A4, S4 -10 Vindrute torkarmekanism	4DR SED 2.0 TDI 6VXL MED MOTOR	Ericssons Bildemontering AB 0370-28100	29.385 A
5028 7841	W98928 500 SEK	Volvo V40 12-19 -14 Vindrute torkarmekanism	5DR CC 1.6 D2 6VXL	Ericssons Bildemontering AB 0370-28100	19.946 A
4687 7841	W14845 500 SEK	Toyota Urban Cruiser -09 Vindrute torkarmekanism	5DR SUV 1,4D TURBO 6VXL	Ericssons Bildemontering AB 0370-28100	20.761 A
2202 7841	W99539 600 SEK	Fiat 500 -12 Vindrute torkarmekanism	3DR CC 1.2MPI 5VXL MED MOTOR	Ericssons Bildemontering AB 0370-28100	11.570 A
5072 7841	W98283 450 SEK	Volvo S60 -06 Vindrute torkarmekanism	4DR SED 2.5T AUTO 4X4	Ericssons Bildemontering AB 0370-28100	28.191 A
3619 7841	W99377 450 SEK	Peugeot 208 -13 Vindrute torkarmekanism	5DR CC 1.2 VTI 5VXL	Ericssons Bildemontering AB 0370-28100	13.631 A
5577 7841	W31181 500 SEK	KIA Cee'd, Cee'd SW -16 Vindrute torkarmekanism	5DR CBI 1.6 CRDI 6VXL	Ericssons Bildemontering AB 0370-28100	11.022 A
3319 7841	W98877 1.250 SEK	Mercedes SLK-Class -08 Vindrute torkarmekanism	2DR CAB 200 K AUTO MED MOTOR	Ericssons Bildemontering AB 0370-28100	23.551 A
1529 7841	W78084 800 SEK	BMW 3-Series -07 Vindrute torkarmekanism	4DR SED 330 3.0XI AUTO MED MOTOR	Ericssons Bildemontering AB 0370-28100	19.280 A
3870 7841	W98695 500 SEK	Renault Kadjar -17 Vindrute torkarmekanism	5DR 1,2TCE 6VXL FWD130HK FWD	Ericssons Bildemontering AB 0370-28100	5.506 A
5073 7841	W98567 450 SEK	Volvo S60 -12 Vindrute torkarmekanism	4DR SED 1,6 T3 6VXL 2WDTRIM LEVEL 2 (MOMENTUM)	Ericssons Bildemontering AB 0370-28100	14.384 A
5077 7841	W98478 400 SEK	Volvo V60 -13 Vindrute torkarmekanism	5DR CBI D4 2.4 6VXL	Ericssons Bildemontering AB 0370-28100	21.575 A
3561 7841	W98260 900 SEK	Opel Zafira -06 Vindrute torkarmekanism	5DR CBI 1.8 5VXL MED MOTOR	Ericssons Bildemontering AB 0370-28100	14.889 A
1439 7841	W51473 800 SEK	Dacia Sandero / Sandero Stepway -16 Vindrute torkarmekanism	5DR CC 1.2TCE 5VXL MED MOTOR	Ericssons Bildemontering AB 0370-28100	8.952 A
5313 7841	W77440 450 SEK	Seat Ibiza -07 Vindrute torkarmekanism	5DR CC 1.4 16V 5VXL	Ericssons Bildemontering AB 0370-28100	15.131 A
2102 7841	W97243 400 SEK	Nissan Almera -01 Vindrute torkarmekanism	5DR CC 1.8 5VXL	Ericssons Bildemontering AB 0370-28100	19.138 A
3689 7841	W97685 400 SEK	Peugeot Partner -11 Vindrute torkarmekanism	5DR SKÅP 1.6 HDI 5VXL 9682861480	Ericssons Bildemontering AB 0370-28100	12.532 A
4929 7841	W67110 450 SEK	VW Passat -14 Vindrute torkarmekanism	5DR CBI 2.0 TDI 6VXL 4WD	Ericssons Bildemontering AB 0370-28100	19.986 A
4207 7841	W79107 450 SEK	Skoda Superb -12 Vindrute torkarmekanism	5DR CBI 2.0TDI AUTO 4WD4WD	Ericssons Bildemontering AB 0370-28100	18.376 A
3861 7841	W9652 1.000 SEK	Renault Megane -11 Vindrute torkarmekanism	5DR CBI 1,6 16V 6VXL	Ericssons Bildemontering AB 0370-28100	13.707 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
3334 7841	W52953 600 SEK	Mercedes C-Class -11 Vindrute torkarmekanism	5DR CBI C220 2.2 CDI AUTOC 220 CDI BLUEEFFICIENCY	Ericssons Bildemontering AB 0370-28100	24.127 A
4973 7841	W77798 400 SEK	VW Caddy -14 Vindrute torkarmekanism	5DR BUSS 2.0ECO 5VXLECOFUEL	Ericssons Bildemontering AB 0370-28100	8.024 A
4318 7841	W96992 600 SEK	Subaru Forester -13 Vindrute torkarmekanism	5DR SUV 2.0D 6VXL 4WD	Ericssons Bildemontering AB 0370-28100	21.059 A
3616 7841	W54735 400 SEK	Peugeot 206 -06 Vindrute torkarmekanism	2DR CAB 1.6 5VXL	Ericssons Bildemontering AB 0370-28100	10.757 A
4948 7841	W24056 500 SEK	VW Golf Plus / Cross Golf -12 Vindrute torkarmekanism	5DR CC 1,6 5VXL VF MED MOTOR	Ericssons Bildemontering AB 0370-28100	26.000 A
2450 7841	W6424 500 SEK	Ford Mondeo -11 Vindrute torkarmekanism	5DR CBI 2.0 TDCI MK2 AUTO	Ericssons Bildemontering AB 0370-28100	31.624 A