

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
1520 7105	W527341 300 SEK	BMW 1-Series -09 Fjäder bak Bak	118D 2.0D 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	20.623 A
1520 7105	W527340 300 SEK	BMW 1-Series -09 Fjäder bak Bak	118D 2.0D 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	20.623 A
1520 7105	W442447 300 SEK	BMW 1-Series -08 Fjäder bak Bak	118D 2.0D 143HK 2.0D/N47-D20A 6VXL 5DR CC DIESEL TESTAD, OK!	Vimmerby Bildemontering AB 0492-20028	9.882 A
1520 7105	W442448 300 SEK	BMW 1-Series -08 Fjäder bak Bak	118D 2.0D 143HK 2.0D/N47-D20A 6VXL 5DR CC DIESEL TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	9.882 A
1520 7105	W441797 300 SEK	BMW 1-Series -07 Fjäder bak Bak	120D 2.0D 177HK 2.0D/N47D20A 6VXL 5DR CC DIESEL TESTAD, OK!	Vimmerby Bildemontering AB 0492-20028	9.048 A
1520 7105	W441796 300 SEK	BMW 1-Series -07 Fjäder bak Bak	120D 2.0D 177HK 2.0D/N47D20A 6VXL 5DR CC DIESEL TESTAD, OK!	Vimmerby Bildemontering AB 0492-20028	9.048 A
1520 7105	W675816 300 SEK	BMW 1-Series -08 Fjäder bak Bak	2.0D 118D KOMBI-SEDAN 143HK 2.0D/N47D20A 6VXL 3DR C TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	22.151 A
1520 7105	W675900 300 SEK	BMW 1-Series -08 Fjäder bak Bak	118 2.0D (E81, E87) 143HK 2.0D/N47-D20A AUTOMAT 5DR TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	25.722 A
1520 7105	W675901 300 SEK	BMW 1-Series -08 Fjäder bak Bak	118 2.0D (E81, E87) 143HK 2.0D/N47-D20A AUTOMAT 5DR TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	25.722 A
1520 7105	W675817 300 SEK	BMW 1-Series -08 Fjäder bak Bak	2.0D 118D KOMBI-SEDAN 143HK 2.0D/N47D20A 6VXL 3DR C TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	22.151 A
1520 7105	W674154 300 SEK	BMW 1-Series -07 Fjäder bak Bak	120I 2.0I KOMBI-SEDAN 150HK 2.0I/N46B20B 6VXL 5DR CC TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	15.693 A
1520 7105	W674155 300 SEK	BMW 1-Series -07 Fjäder bak Bak	120I 2.0I KOMBI-SEDAN 150HK 2.0I/N46B20B 6VXL 5DR CC TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	15.693 A
1520 7105	W673936 300 SEK	BMW 1-Series -11 Fjäder bak Bak	116 2.0D E81 E87 116HK 2.0D/N47-D20C 6VXL 5DR CSE D TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	26.717 A
1520 7105	W673937 300 SEK	BMW 1-Series -11 Fjäder bak Bak	116 2.0D E81 E87 116HK 2.0D/N47-D20C 6VXL 5DR CSE D TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	26.717 A
1520 7105	W651820 300 SEK	BMW 1-Series -07 Fjäder bak Bak	118 2.0D CC SEDAN 143HK 2.0D/N47D20A 6VXL 5DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.680 A
1520 7105	W651821 300 SEK	BMW 1-Series -07 Fjäder bak Bak	118 2.0D CC SEDAN 143HK 2.0D/N47D20A 6VXL 5DR CC DI TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	26.680 A
1520 7105	W645517 300 SEK	BMW 1-Series -08 Fjäder bak Bak	2.0D CC 177HK 2.0D/N47D20A 6VXL 5DR CC DIESEL TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	25.860 A
1520 7105	W636691 300 SEK	BMW 1-Series -11 Fjäder bak Bak	118 2.0D CC 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	14.000 A
1520 7105	W636692 300 SEK	BMW 1-Series -11 Fjäder bak Bak	118 2.0D CC 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	14.000 A
1520 7105	W635198 300 SEK	BMW 1-Series -09 Fjäder bak Bak	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 7105	W635199 300 SEK	BMW 1-Series -09 Fjäder bak Bak	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 7105	W613398 300 SEK	BMW 1-Series -09 Fjäder bak Bak	118D 2.0D DIESEL CC 143HK 2.0D/N47D20C 6VXL 3DR CC TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	25.743 A
1520 7105	W565012 300 SEK	BMW 1-Series -09 Fjäder bak Bak	118 2.0D 143HK 2.0D/N47D20C 6VXL/GS817DG 5DR CC DIE TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	14.089 A
1520 7105	W565013 300 SEK	BMW 1-Series -09 Fjäder bak Bak	118 2.0D 143HK 2.0D/N47D20C 6VXL/GS817DG 5DR CC DIE TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	14.089 A