

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
1520 5042	W546872 500 SEK	BMW 1-Series -11 Bakljus Höger	116 2.0D KOMBI-SEDAN 116HK 2.0D/N47D20C 6VXL/GS617D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	8.313 A
1520 5042	W540380 500 SEK	BMW 1-Series -07 Bakljus Höger	120 2.0D DIESEL 177HK 2.0D/N47D20A AUT/GA6HP19Z 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.415 A
1520 5042	W527358 500 SEK	BMW 1-Series -09 Bakljus Höger	118D 2.0D 143HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	20.623 A
1520 5042	W397629 500 SEK	BMW 1-Series -07 Bakljus Höger	120 2.0D 163HK 5DR CC-KAROSS 2.0D/N47TU2D20 AUTOMAT TESTAD, OK	Vimmerby Bildemontering AB 0492-20028	17.827 A
1520 5042	W673911 500 SEK	BMW 1-Series -11 Bakljus Höger	116 2.0D E81 E87 116HK 2.0D/N47-D20C 6VXL 5DR CSE D TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	26.717 A
1520 5042	W651795 500 SEK	BMW 1-Series -07 Bakljus Höger	118 2.0D CC SEDAN 143HK 2.0D/N47D20A 6VXL 5DR CC DI TESTAD OK	Vimmerby Bildemontering AB 0492-20028	26.680 A
1520 5042	W635177 500 SEK	BMW 1-Series -09 Bakljus Höger	120 2.0D CC 177HK 2.0D/N47D20C 6VXL 5DR CC DIESEL TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	18.752 A
1520 5042	W614035 500 SEK	BMW 1-Series -07 Bakljus Höger	120 2.0D DIESEL CC 163HK 2.0D/N47TU2D20 6VXL 5DR CC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	17.600 A
1520 5042	W613404 500 SEK	BMW 1-Series -09 Bakljus Höger	118D 2.0D DIESEL CC 143HK 2.0D/N47D20C 6VXL 3DR CC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.743 A
1520 5042	W594984 500 SEK	BMW 1-Series -04 Bakljus Höger	TESTAD OK	Vimmerby Bildemontering AB 0492-20028	- A