

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
5319 7450	W724370	Seat Arona -19 Tändspole	1.0 TSI CROSSOVER 95HK 1.0DKLA 5VXL 5DR SUV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.503 A
5319 7450	W724372	Seat Arona -19 Tändspole	1.0 TSI CROSSOVER 95HK 1.0DKLA 5VXL 5DR SUV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.503 A
5319 7450	W724371	Seat Arona -19 Tändspole	1.0 TSI CROSSOVER 95HK 1.0DKLA 5VXL 5DR SUV BENSIN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.503 A
5319 7450	W708535	Seat Arona -19 Tändspole	1.0 TSI CROSSOVER 70HK 1.0TSI/DKLA 5VXL 5DR SUV BEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.900 A
5319 7450	W708534	Seat Arona -19 Tändspole	1.0 TSI CROSSOVER 70HK 1.0TSI/DKLA 5VXL 5DR SUV BEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.900 A
5319 7450	W708536	Seat Arona -19 Tändspole	1.0 TSI CROSSOVER 70HK 1.0TSI/DKLA 5VXL 5DR SUV BEN TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.900 A
5319 7450	W636352 250 SEK	Seat Arona -20 Tändspole	1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	- A
5319 7450	W636351 250 SEK	Seat Arona -20 Tändspole	1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	- A
5319 7450	W636353 250 SEK	Seat Arona -20 Tändspole	1.0TGI CROSSOVER 90HK 1.0TGI/DBYA 5VXL CC CNG TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	- A