

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
5319 7463	W724430	Seat Arona -19 Lambdasond	1.0 TSI CROSSOVER 95HK 1.0/DKLA 5VXL 5DR SUV BENSIN FRÄMRE TESTAD OK FRÄMRE	Vimmerby Bildemontering AB 0492-20028	13.503 A
5319 7463	W724428	Seat Arona -19 Lambdasond	1.0 TSI CROSSOVER 95HK 1.0/DKLA 5VXL 5DR SUV BENSIN BAKRE TESTAD OK BAKRE	Vimmerby Bildemontering AB 0492-20028	13.503 A
5319 7463	W708554	Seat Arona -19 Lambdasond	1.0 TSI CROSSOVER 70HK 1.0/TSI/DKLA 5VXL 5DR SUV BEN BAKRE TESTAD OK BAKRE	Vimmerby Bildemontering AB 0492-20028	7.900 A
5319 7463	W636355	Seat Arona -20 Lambdasond	1.0 TGI CROSSOVER 90HK 1.0/TGI/DBYA 5VXL CC CNG BAKRE TESTAD OK BAKRE	Vimmerby Bildemontering AB 0492-20028	- A
5319 7463	W636356	Seat Arona -20 Lambdasond	1.0 TGI CROSSOVER 90HK 1.0/TGI/DBYA 5VXL CC CNG FRÄMRE TESTAD OK FRÄMRE	Vimmerby Bildemontering AB 0492-20028	- A