

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4949 7118	W735865 625 SEK	VW Golf, e-Golf -19 Stötdämpare bak Bak	1.6 TDI DIESEL VARIANT 116HK 1.6/DGTE AUTOMAT 5DR H EJ NIVÅREGLERING TESTAD OK EJ NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	18.839 A
4949 7118	W735866 625 SEK	VW Golf, e-Golf -19 Stötdämpare bak Bak	1.6 TDI DIESEL VARIANT 116HK 1.6/DGTE AUTOMAT 5DR H EJ NIVÅREGLERING TESTAD OK EJ NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	18.839 A
4949 7118	W732382 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	2.0 GTD 4-M CROSSOVER 184HK 2.0/DGCA AUTOMAT 5DR HG NIVÅREGLERING TESTAD OK NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	5.915 A
4949 7118	W732381 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	2.0 GTD 4-M CROSSOVER 184HK 2.0/DGCA AUTOMAT 5DR HG NIVÅREGLERING TESTAD OK NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	5.915 A
4949 7118	W731458 300 SEK	VW Golf, e-Golf -19 Stötdämpare bak Bak	1.5 TGI VARIANT BIOGAS 131HK 1.5/TGIDHFA 6VXL/SEL 5 EJ NIVÅREGLERING TESTAD OK EJ NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	4.960 A
4949 7118	W731457 300 SEK	VW Golf, e-Golf -19 Stötdämpare bak Bak	1.5 TGI VARIANT BIOGAS 131HK 1.5/TGIDHFA 6VXL/SEL 5 EJ NIVÅREGLERING TESTAD OK EJ NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	4.960 A
4949 7118	W703578 300 SEK	VW Golf, e-Golf -15 Stötdämpare bak Bak	1.4 TGI BIFUEL VARIANT 110HK 1.4/CPWA AUTOMAT 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	16.011 A
4949 7118	W703577 300 SEK	VW Golf, e-Golf -15 Stötdämpare bak Bak	1.4 TGI BIFUEL VARIANT 110HK 1.4/CPWA AUTOMAT 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	16.011 A
4949 7118	W703116 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4 TGI BIFUEL KOMBI-SED 110HK 1.4/CPWA 6VXL 5DR CSE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.549 A
4949 7118	W703115 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4 TGI BIFUEL KOMBI-SED 110HK 1.4/CPWA 6VXL 5DR CSE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	13.549 A
4949 7118	W693677 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4 TSI MULTIFUEL KOM-SED 125HK 1.4/TSI/CPVB 6VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	2.132 A
4949 7118	W693676 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4 TSI MULTIFUEL KOM-SED 125HK 1.4/TSI/CPVB 6VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	2.132 A
4949 7118	W692857 300 SEK	VW Golf, e-Golf -16 Stötdämpare bak Bak	1.6 TDI DIESEL VARIANT 110HK 1.6/TDI/DBKA 6VXL 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	10.932 A
4949 7118	W692856 300 SEK	VW Golf, e-Golf -16 Stötdämpare bak Bak	1.6 TDI DIESEL VARIANT 110HK 1.6/TDI/DBKA 6VXL 5DR H TESTAD OK	Vimmerby Bildemontering AB 0492-20028	10.932 A
4949 7118	W689281 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4 TGI BIFUEL KOMBI-SEDAN 110HK 1.4/TSI/CPWA 6VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	3.552 A
4949 7118	W686438 300 SEK	VW Golf, e-Golf -14 Stötdämpare bak Bak	1.6 TDI DIESEL KOMBI-SEDAN 105HK 1.6/TDI/CLHA AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	10.009 A
4949 7118	W686437 300 SEK	VW Golf, e-Golf -14 Stötdämpare bak Bak	1.6 TDI DIESEL KOMBI-SEDAN 105HK 1.6/TDI/CLHA AUTOMAT TESTAD OK	Vimmerby Bildemontering AB 0492-20028	10.009 A
4949 7118	W685978 300 SEK	VW Golf, e-Golf -14 Stötdämpare bak Bak	1.4 TSI MULTIFUEL 122HK 1.4/TSI/CPVA 6VXL 5DR CSE ETA TESTAD OK	Vimmerby Bildemontering AB 0492-20028	18.000 A
4949 7118	W672959 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	2.0 TDI 4-MOTION DIESEL 150HK 2.0/TDI/DCYA 6VXL 5DR C TESTAD OK	Vimmerby Bildemontering AB 0492-20028	8.692 A
4949 7118	W672958 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	2.0 TDI 4-MOTION DIESEL 150HK 2.0/TDI/DCYA 6VXL 5DR C TESTAD OK	Vimmerby Bildemontering AB 0492-20028	8.692 A
4949 7118	W672256 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	1.2 TSI VARIANT 110HK 1.2/TSI/CYVB 6VXL 5DR HGV BENS TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	6.498 A
4949 7118	W665904 300 SEK	VW Golf, e-Golf -16 Stötdämpare bak Bak	1.4 TSI VARIANT 125HK 1.4/TSI/CPVB 6VXL 5DR HGV ETANO TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.575 A
4949 7118	W649212 400 SEK	VW Golf, e-Golf -15 Stötdämpare bak Bak	1.4 TSI CC 103HK 1.4/TSI/CHPA 6VXL 5DR CC BENSIN TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	15.500 A
4949 7118	W649213 400 SEK	VW Golf, e-Golf -15 Stötdämpare bak Bak	1.4 TSI CC 103HK 1.4/TSI/CHPA 6VXL 5DR CC BENSIN TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	15.500 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4949 7118	W647828 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	2.0T R-4-MOTION CC 301HK 2.0T/CJXC AUTOMAT 5DR CC B TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	6.822 A
4949 7118	W647827 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	2.0T R-4-MOTION CC 301HK 2.0T/CJXC AUTOMAT 5DR CC B TESTAD OK!	Vimmerby Bildemontering AB 0492-20028	6.822 A
4949 7118	W636463 300 SEK	VW Golf, e-Golf -15 Stötdämpare bak Bak	1.6TDI DIESEL VARIANT 105HK 1.6TDI/CLHA AUTOMAT 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.460 A
4949 7118	W602544 300 SEK	VW Golf, e-Golf -16 Stötdämpare bak Bak	1.4TSI KOMBI 150HK GAS 1.4TSI/CPWA AUTOMAT 5DR HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.980 A
4949 7118	W602543 300 SEK	VW Golf, e-Golf -16 Stötdämpare bak Bak	1.4TSI KOMBI 150HK GAS 1.4TSI/CPWA AUTOMAT 5DR HGV TESTAD OK	Vimmerby Bildemontering AB 0492-20028	25.980 A
4949 7118	W601676 300 SEK	VW Golf, e-Golf -14 Stötdämpare bak Bak	1.6TDI CC 110HK 1.6TDI/CRKB 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	11.139 A
4949 7118	W601677 300 SEK	VW Golf, e-Golf -14 Stötdämpare bak Bak	1.6TDI CC 110HK 1.6TDI/CRKB 6VXL 5DR CC DIESEL TESTAD OK	Vimmerby Bildemontering AB 0492-20028	11.139 A
4949 7118	W594509 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	1.4TSI VARIANT 150HK 1.4TSI/CZDA AUTOMAT 5DR CBI BE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.100 A
4949 7118	W594508 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	1.4TSI VARIANT 150HK 1.4TSI/CZDA AUTOMAT 5DR CBI BE TESTAD OK	Vimmerby Bildemontering AB 0492-20028	7.100 A
4949 7118	W581566 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	1.4TSI KOMBI-SEDAN 125HK 1.4TSI/CPVB 6VXL 5DR CC ET TESTAD OK	Vimmerby Bildemontering AB 0492-20028	3.866 A
4949 7118	W581565 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	1.4TSI KOMBI-SEDAN 125HK 1.4TSI/CPVB 6VXL 5DR CC ET TESTAD OK	Vimmerby Bildemontering AB 0492-20028	3.866 A
4949 7118	W581113 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	1.4TSI BIFUEL VARIANT 110HK 1.4TSI/CPWA 6VXL/SEH 5D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.322 A
4949 7118	W581114 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	1.4TSI BIFUEL VARIANT 110HK 1.4TSI/CPWA 6VXL/SEH 5D TESTAD OK	Vimmerby Bildemontering AB 0492-20028	22.322 A
4949 7118	W576484 300 SEK	VW Golf, e-Golf -19 Stötdämpare bak Bak	1.4 GTE HYBRID CC 150HK 1.4I/CUKB AUTOMAT/TEA 5DR C TESTAD OK	Vimmerby Bildemontering AB 0492-20028	826 A
4949 7118	W576483 300 SEK	VW Golf, e-Golf -19 Stötdämpare bak Bak	1.4 GTE HYBRID CC 150HK 1.4I/CUKB AUTOMAT/TEA 5DR C TESTAD OK	Vimmerby Bildemontering AB 0492-20028	826 A
4949 7118	W574582 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4TSI MULTIFUEL CC 125HK 1.4TSI/CPVB 6VXL/SEH 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	864 A
4949 7118	W574581 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4TSI MULTIFUEL CC 125HK 1.4TSI/CPVB 6VXL/SEH 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	864 A
4949 7118	W573330 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	2.0GTI KOMBI-SEDAN 265HK 2.0GTI/CJXE AUTOMAT 5DR CC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	2.437 A
4949 7118	W573331 300 SEK	VW Golf, e-Golf -17 Stötdämpare bak Bak	2.0GTI KOMBI-SEDAN 265HK 2.0GTI/CJXE AUTOMAT 5DR CC TESTAD OK	Vimmerby Bildemontering AB 0492-20028	2.437 A
4949 7118	W572981 300 SEK	VW Golf, e-Golf -14 Stötdämpare bak Bak	1.6TDI 4MOTION KOMBI 105HK 1.6TDI/CLHA 6VXL/MRV 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.675 A
4949 7118	W572982 300 SEK	VW Golf, e-Golf -14 Stötdämpare bak Bak	1.6TDI 4MOTION KOMBI 105HK 1.6TDI/CLHA 6VXL/MRV 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	14.675 A
4949 7118	W568814 300 SEK	VW Golf, e-Golf -15 Stötdämpare bak Bak	1.2TSI KOMBI-SEDAN 105HK 1.2TSI/CJZA 6VXL/PRL 5DR C TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.138 A
4949 7118	W568815 300 SEK	VW Golf, e-Golf -15 Stötdämpare bak Bak	1.2TSI KOMBI-SEDAN 105HK 1.2TSI/CJZA 6VXL/PRL 5DR C TESTAD OK	Vimmerby Bildemontering AB 0492-20028	15.138 A
4949 7118	W468229 300 SEK	VW Golf, e-Golf -13 Stötdämpare bak Bak	1.6TDI 4-MOTION 1.6TDI/CLHA 6VXL/MRV 5DR CC DIESEL	Vimmerby Bildemontering AB 0492-20028	5.516 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4949 7118	W719709 300 SEK	VW Golf, e-Golf -14 Stötdämpare bak Bak	1.4TSI MULTIFUEL KOM-SED 122HK 1.4/CPVA 6VXL 5DR CS EJ NIVÅREGLERING TESTAD OK EJ NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	6.863 A
4949 7118	W719710 300 SEK	VW Golf, e-Golf -14 Stötdämpare bak Bak	1.4TSI MULTIFUEL KOM-SED 122HK 1.4/CPVA 6VXL 5DR CS EJ NIVÅREGLERING TESTAD OK EJ NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	6.863 A
4949 7118	W715744 300 SEK	VW Golf, e-Golf -19 Stötdämpare bak Bak	1.6 TDI DIESELKOMBISEDAN 116HK 1.6TDI/DGTE 6VXL 5DR EJ NIVÅREGLERING TESTAD OK EJ NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	7.994 A
4949 7118	W715745 300 SEK	VW Golf, e-Golf -19 Stötdämpare bak Bak	1.6 TDI DIESELKOMBISEDAN 116HK 1.6TDI/DGTE 6VXL 5DR EJ NIVÅREGLERING TESTAD OK EJ NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	7.994 A
4949 7118	W708326 300 SEK	VW Golf, e-Golf -15 Stötdämpare bak Bak	2.0 TDI DIESEL 4-MOTION 150HK 2.0/CRLB 6VXL 5DR HGV NIVÅREGLERING TESTAD OK NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	12.942 A
4949 7118	W708325 300 SEK	VW Golf, e-Golf -15 Stötdämpare bak Bak	2.0 TDI DIESEL 4-MOTION 150HK 2.0/CRLB 6VXL 5DR HGV NIVÅREGLERING TESTAD OK NIVÅREGLERING	Vimmerby Bildemontering AB 0492-20028	12.942 A
4949 7118	W707292 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	2.0 TDI 4-MOTION VARIANT 150HK 2.0TDI/DCYA 6VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.288 A
4949 7118	W707293 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	2.0 TDI 4-MOTION VARIANT 150HK 2.0TDI/DCYA 6VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	9.288 A
4949 7118	W707117 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4TSI MULTIFUEL VARIANT 125HK 1.4/CPVB 6VXL 5DR HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	4.493 A
4949 7118	W707118 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4TSI MULTIFUEL VARIANT 125HK 1.4/CPVB 6VXL 5DR HG TESTAD OK	Vimmerby Bildemontering AB 0492-20028	4.493 A
4949 7118	W689278 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4 TGI BIFUEL KOMBISEDAN 110HK 1.4TGI/CPWA 6VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	- A
4949 7118	W689277 300 SEK	VW Golf, e-Golf -18 Stötdämpare bak Bak	1.4 TGI BIFUEL KOMBISEDAN 110HK 1.4TGI/CPWA 6VXL 5DR TESTAD OK	Vimmerby Bildemontering AB 0492-20028	- A