

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
5203 5013	W1036177 2.500 SEK	Hyundai Getz -08 Baklucka CC / Kombi-Sedan	HYUNDAI GETZ 5D 1.4 M5ZT G4EE 5VXL 5DR CSE BENSIN	Norrbottns Bildemontering AB 0929-70000	7.397 A
2418 5013	W1017855 5.000 SEK	Ford Fiesta -14 Baklucka CC / Kombi-Sedan	FORD FIESTA 1.25I 82HK 5VXL 5DR CSE BENSIN	Norrbottns Bildemontering AB 0929-70000	5.219 A
4555 5013	W1008550 2.995 SEK	Toyota Yaris -18 Baklucka CC / Kombi-Sedan	TOYOTA YARIS HYBRID 1.5 HYB 73HK HYBRID 5DR CSE ELH	Norrbottns Bildemontering AB 0929-70000	3.138 A
3827 5013	W998182 2.915 SEK	Renault Clio -19 Baklucka CC / Kombi-Sedan	RENAULT CLIO 0.9 T 0.9TCE 76HK 5VXL 5DR CSE BENSIN EJ FÖR KAMERA	Norrbottns Bildemontering AB 0929-70000	2.816 A
4220 5013	W994341 5.750 SEK	Skoda Superb -17 Baklucka CC / Kombi-Sedan	SKODA SUPERB 2.0TDI DSG 4WD 5DR CSE DIESEL	Norrbottns Bildemontering AB 0929-70000	12.239 A
5285 5013	W962748 1.995 SEK	Hyundai i20 -15 Baklucka CC / Kombi-Sedan	HYUNDAI I20 1.2I 5VXL 5DR CSE BENSIN	Norrbottns Bildemontering AB 0929-70000	3.781 A
5052 5013	W958502 2.995 SEK	Volvo C30 -08 Baklucka CC / Kombi-Sedan	C30 1.8F 5VXL 3DRS CC 1.8F 92KW 5VXL 3DR CSE ETANOL GRÖNTONAD RUTA	Norrbottns Bildemontering AB 0929-70000	13.167 A
2523 5013	W944756 2.995 SEK	Chevrolet Corvette -98 Baklucka CC / Kombi-Sedan	CHEVROLET CORVETTE 5.7I V8 344HK AUTOMAT 2DR CPE BE	Norrbottns Bildemontering AB 0929-70000	21.535 A
4555 5013	W941207 2.995 SEK	Toyota Yaris -20 Baklucka CC / Kombi-Sedan	TOYOTA YARIS 1.5I 112HK AUT 5DR CSE BENSIN FÖR SPOILER MED BACKKAMERA	Norrbottns Bildemontering AB 0929-70000	621 A
4555 5013	W933301 2.995 SEK	Toyota Yaris -19 Baklucka CC / Kombi-Sedan	TOYOTA YARIS HYBRID 1.5I HYBR 73HK AUT 5DR CSE ELHY FÖR BACKKAMERA	Norrbottns Bildemontering AB 0929-70000	1.127 A
4489 5013	W927356 10.000 SEK	Toyota Corolla -19 Baklucka CC / Kombi-Sedan	TOYOTA COROLLA 1.8 HYBRID 98HK AUT 5DR CSE ELHYBRID	Norrbottns Bildemontering AB 0929-70000	697 A
5291 5013	W926893 2.500 SEK	Hyundai i30 -15 Baklucka CC / Kombi-Sedan	HYUNDAI I30 1.6CRDI 110HK 6VXL 5DR CSE DIESEL MED RUTA	Norrbottns Bildemontering AB 0929-70000	5.995 A
5052 5013	W888913 2.995 SEK	Volvo C30 -07 Baklucka CC / Kombi-Sedan	C30 2.0 145HK 5VXL 2.0 145HK 5VXL 3DR CSE BENSIN MED SPOILER 39880474	Norrbottns Bildemontering AB 0929-70000	11.343 A
3862 5013	W873908 2.990 SEK	Renault Megane -17 Baklucka CC / Kombi-Sedan	MEGANE 1,5DCI AUT 5D CC 1,5DCI AUT CC INNERDEL MED RUTA	Norrbottns Bildemontering AB 0929-70000	2.466 A
5577 5013	W862837 3.000 SEK	KIA Cee'd, Cee'd SW -13 Baklucka CC / Kombi-Sedan	KIA CEED 1,6D R4 128HK 6VXL 5DR CSE DIESEL MED RUTA	Norrbottns Bildemontering AB 0929-70000	3.229 A
5053 5013	W832339 3.000 SEK	Volvo C30 -10 Baklucka CC / Kombi-Sedan	VOLVO C30 2.0D AUT 136HK 3DRS 2.0D R4 136HK TIPTRON GRÖNTONAD BAKDÖRR/BAKRUTA	Norrbottns Bildemontering AB 0929-70000	9.197 A
1440 5013	W810395 1.695 SEK	Dacia Sandero -10 Baklucka CC / Kombi-Sedan	DACIA 5VXL 5D 1,6I 8V E85 1,6 8V E85 5VXL 5DR CSE E MED RUTA	Norrbottns Bildemontering AB 0929-70000	10.801 A
4547 5013	W790813 2.750 SEK	Toyota Prius -10 Baklucka CC / Kombi-Sedan	TOYOTA PRIUS XW3 1.8 HYBRID 98HK AUT 5DR CSE ELHYBR MED RUTOR	Norrbottns Bildemontering AB 0929-70000	8.310 A
1352 5013	W493667 2.995 SEK	Audi A1 / S1 -11 Baklucka CC / Kombi-Sedan	AUDI A1 8X CAYC 5VXL 2DR CC DIESEL 3DRS MED RUTA	Norrbottns Bildemontering AB 0929-70000	1.445 A
4674 5013	W1071293	Toyota Yaris -21 Baklucka CC / Kombi-Sedan	TOYOTA YARIS M15A-FXE V 5DR CSE ELHYBRID B GRÖVRE REPOR GENOM LACK	Norrbottns Bildemontering AB 0929-70000	908 M
2732 5013	W1070194	Honda Civic -17 Baklucka CC / Kombi-Sedan	HONDA CIVIC 4DR L 15B7 V 4DR SED BENSIN LITE FALSROST + PETAT KIT 20P, SEDAN	Norrbottns Bildemontering AB 0929-70000	6.012 M
1532 5013	W1066456 3.750 SEK	BMW 3-Series -18 Baklucka CC / Kombi-Sedan	BMW 320D XDRIVE B47-D20A A 5DR CSE DIESEL	Norrbottns Bildemontering AB 0929-70000	13.282 A*
2473 5013	W1066513	Ford Focus -13 Baklucka CC / Kombi-Sedan	FORD FOCUS M2DA M 5DR CSE BENSIN PETAT KITT EJ ANGRIPEN FALS, AVDRAG 20P	Norrbottns Bildemontering AB 0929-70000	13.324 M
3821 5013	W1061158 2.900 SEK	Renault Zoe -19 Baklucka CC / Kombi-Sedan	RENAULT ZOE 5AQC-60 5DR CSE EL AVDRAG FÖR ANGRIPEN FALS 120P	Norrbottns Bildemontering AB 0929-70000	1.002 M

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4949 5013	W1060566 5.740 SEK	VW Golf, e-Golf -15 Baklucka CC / Kombi-Sedan	VOLKSWAGEN GOLF CRKB M 5DR CSE DIESEL	Norrbottens Bildemontering AB 0929-70000	14.513 M
5282 5013	W1059062 4.400 SEK	Hyundai i10 -15 Baklucka CC / Kombi-Sedan	HYUNDAI I10 G4LA M 5DR CSE BENSIN	Norrbottens Bildemontering AB 0929-70000	6.136 M
3514 5013	W1056942 3.925 SEK	Opel Corsa -12 Baklucka CC / Kombi-Sedan	OPEL CORSA A12XER M 5DR CSE BENSIN	Norrbottens Bildemontering AB 0929-70000	4.022 A*
1522 5013	W1055925 3.475 SEK	BMW 1-Series -12 Baklucka CC / Kombi-Sedan	BMW 118D 2.0D 143HK 6VXL 5DR CSE DIESEL PETAT KITT, LÄTT ANGRIPEN FALS, AVDRAG 108P,EJ RUT	Norrbottens Bildemontering AB 0929-70000	7.991 M
3631 5013	W1045666 8.125 SEK	Peugeot 308 -08 Baklucka CC / Kombi-Sedan	AVDRAG YTROST+PETAT KITT 120P. VF34C5FXC550085113	Norrbottens Bildemontering AB 0929-70000	- M
4949 5013	W1042300 5.000 SEK	VW Golf, e-Golf -14 Baklucka CC / Kombi-Sedan	VOLKSWAGEN GOLF CLHA M 5DR CSE DIESEL GALVSLÄPP VID BROMSLJUS+BÄKLJUS, AVDRAG 60P	Norrbottens Bildemontering AB 0929-70000	10.975 M