

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
5058 8009	W1071594 2.375 SEK	Volvo S80 -04 AC Kondensork/Kylare	VOLVO S80 B5254T2 A 4DR SED BENSIN	Norrbottens Bildemontering AB 0929-70000	26.000 A*
4674 8009	W1071577	Toyota Yaris -21 AC Kondensork/Kylare	TOYOTA YARIS M15A-FXE V 5DR CSE ELHYBRID B	Norrbottens Bildemontering AB 0929-70000	908 A*
5233 8009	W1069936	Hyundai ix20 -11 AC Kondensork/Kylare	HYUNDAI IX20 D4FC M 5DR SUV DIESEL	Norrbottens Bildemontering AB 0929-70000	10.580 A*
3449 8009	W1066171 6.250 SEK	Mitsubishi Outlander -20 AC Kondensork/Kylare	MITSUBISHI OUTLANDER 4B12 A 5DR SUV ELHYBRID B	Norrbottens Bildemontering AB 0929-70000	4.174 A*
1707 8009	W1065266 3.095 SEK	Citroen Berlingo -18 AC Kondensork/Kylare	CITROEN BERLINGO BHY M 5DR SKP DIESEL BEHR	Norrbottens Bildemontering AB 0929-70000	6.522 A*
3702 8009	W1065478 4.220 SEK	Porsche Cayenne -13 AC Kondensork/Kylare	PORSCHE CAYENNE DIESEL 92A V6 DIESEL AUT 4WD 5DR SU DELPHI	Norrbottens Bildemontering AB 0929-70000	16.984 A*
1441 8009	W1064876 745 SEK	Dacia Logan MCV/Stepway -09 AC Kondensork/Kylare	DACIA LOGAN MCV K4M-696 M 5DR SKP ETANOL E85 NISSENS	Norrbottens Bildemontering AB 0929-70000	29.057 A*
5071 8009	W1061165 2.375 SEK	Volvo S60 -04 AC Kondensork/Kylare	VOLVO S60 B5244S 5VXL 4DR SED BENSIN	Norrbottens Bildemontering AB 0929-70000	24.509 A*
2781 8009	W1058416 2.395 SEK	Honda HR-V -19 AC Kondensork/Kylare	HONDA HR-V 1,5I 131HK 6VXL 5DR SUV BENSIN	Norrbottens Bildemontering AB 0929-70000	4.951 A*
3631 8009	W1052222 1.495 SEK	Peugeot 308 -08 AC Kondensork/Kylare	PEUGEOT 308 SW 2,0 BIOFL 2.0I 140HK 5VXL 5DR CBI ET BEHR	Norrbottens Bildemontering AB 0929-70000	15.107 A*
2168 8009	W1051595 1.875 SEK	Nissan Pulsar -16 AC Kondensork/Kylare	NISSAN PULSAR HRA2 M 5DR CSE BENSIN	Norrbottens Bildemontering AB 0929-70000	3.638 A
1264 8009	W1048844 2.495 SEK	Jeep Grand Cherokee -18 AC Kondensork/Kylare	JEEP GRAND CHEROKEE M A 5DR SUV DIESEL	Norrbottens Bildemontering AB 0929-70000	8.151 A*
5062 8009	W1048363 2.375 SEK	Volvo V70 -05 AC Kondensork/Kylare	VOLVO V70 B5244S2 M 5DR CBI BENSIN	Norrbottens Bildemontering AB 0929-70000	33.027 A*
4997 8009	W1040752 2.495 SEK	VW Transporter/Caravelle -17 AC Kondensork/Kylare	VOLKSWAGEN TRANSPORTER CXFA A 0DR BUS DIESEL	Norrbottens Bildemontering AB 0929-70000	49.107 A*
8589 8009	W1040455 2.125 SEK	Husbil Knaus -05 AC Kondensork/Kylare	RENAULT KNAUS SUN TR 650 3,0DCI 136HK 6VXL 0DR HUB VALEO	Norrbottens Bildemontering AB 0929-70000	12.968 A*
4962 8009	W1038124 995 SEK	VW Touran -15 AC Kondensork/Kylare	VW TOURAN CTHC M 5DR CBI BENSIN	Norrbottens Bildemontering AB 0929-70000	23.476 A*
2807 8009	W1037646 2.995 SEK	Isuzu D-Max -19 AC Kondensork/Kylare	ISUZU D-MAX 1,9DDI AUT 4WD 4DR PIC DIESEL	Norrbottens Bildemontering AB 0929-70000	3.904 A*
2791 8009	W1026762 995 SEK	Honda CR-V -14 AC Kondensork/Kylare	HONDA CR-V R20A9 AUTOMAT 5DR SUV BENSIN	Norrbottens Bildemontering AB 0929-70000	5.418 A*
4995 8009	W1022798 695 SEK	VW Transporter/Caravelle -02 AC Kondensork/Kylare	VW CARAVELLE 2,5 2.5I M 3DR SKP BENSIN LÅNGA FRONTEN	Norrbottens Bildemontering AB 0929-70000	31.985 A*
2807 8009	W1021978 3.095 SEK	Isuzu D-Max -17 AC Kondensork/Kylare	ISUZU D-MAX 1,9DDI 163HK 6VXL 4WD 4DR PIC DIESEL	Norrbottens Bildemontering AB 0929-70000	10.202 A*
4568 8009	W1019241 1.000 SEK	Toyota Avensis -08 AC Kondensork/Kylare	TOYOTA AVENSIS 2.0I 146HK 5VXL 5DR CBI BENSIN NISSENS UTBYTES	Norrbottens Bildemontering AB 0929-70000	13.662 A*
1712 8009	W1018291 1.500 SEK	Citroen C5 -14 AC Kondensork/Kylare	CITROEN C5 4HL 5DR CBI DIESEL NISSENS EJ ORIGINAL PASSAR 6455HR, 9816999380	Norrbottens Bildemontering AB 0929-70000	15.982 A*
2168 8009	W1018306 1.800 SEK	Nissan Pulsar -15 AC Kondensork/Kylare	NISSAN PULSAR TEKNA 6VXL 1,2T HRA2DDT 6VXL 5DR CSE	Norrbottens Bildemontering AB 0929-70000	5.902 A*
2473 8009	W1016042 1.490 SEK	Ford Focus -13 AC Kondensork/Kylare	WF0LXXGCBLDB68264	Norrbottens Bildemontering AB 0929-70000	- A*

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4568 8009	W1013545 1.000 SEK	Toyota Avensis -07 AC Kondensator/Kylare	TOYOTA AVENSIS 1AZ-FSE A 5DR CBI BENSIN NISSENS UTBYTES EJ ORIGINAL. PASSAR 88450-05121	Norrbottens Bildemontering AB 0929-70000	24.823 A*
2596 8009	W1011801 1.250 SEK	Chevrolet Trax -14 AC Kondensator/Kylare	CHEVROLET TRAX 2VD 1,7CDTI AUT 2VD 5DR SUV DIESEL	Norrbottens Bildemontering AB 0929-70000	9.650 A*
2179 8009	W1008804 995 SEK	Nissan Qashqai+2 -12 AC Kondensator/Kylare	NISSAN QASHQAI+2 2.0DCI 150HK AUT 4WD 5DR SUV DIESE NISSENS EJ ORIGINAL. PASSAR 92100-BR40A	Norrbottens Bildemontering AB 0929-70000	19.915 A*
5345 8009	W1008251 600 SEK	Seat Exeo -10 AC Kondensator/Kylare	SEAT EXEO ST KOMBI 1,8T 150HK M 5DR CBI BENSIN NISSENS EJ ORIGINAL. PASSAR 8E0260403T	Norrbottens Bildemontering AB 0929-70000	24.505 A*
4553 8009	W1001931 995 SEK	Toyota Corolla -06 AC Kondensator/Kylare	TOYOTA COROLLA 1.6I 5VXL 5DR CSE BENSIN	Norrbottens Bildemontering AB 0929-70000	15.434 A*
2388 8009	W993335 2.995 SEK	Ford Ranger -12 AC Kondensator/Kylare	FORD RANGER 3.2TDCI 200HK 6VXL 4WD 4DR DBH DIESEL	Norrbottens Bildemontering AB 0929-70000	1.707 A*