

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
1540 5076	W1074305	BMW 5-Series -14 Spolarpump Baklucka	BMW 520D XDRIVE N47-D20C A 5DR CBI DIESEL	Norrbottns Bildemontering AB 0929-70000	17.477 A
1511 5076	W1071609	BMW X3 -12 Spolarpump Baklucka	BMW X3 XDRIVE 20D N47-D20C A 5DR SUV DIESEL	Norrbottns Bildemontering AB 0929-70000	29.879 A
4303 5076	W1066825 170 SEK	Subaru Outback -11 Spolarpump Baklucka	SUBARU OUTBACK EE20 5DR CBI DIESEL VINDRUTA/BAKRUTA	Norrbottns Bildemontering AB 0929-70000	27.407 A
4544 5076	W1065711 295 SEK	Toyota Verso -12 Spolarpump Baklucka	TOYOTA VERSO 2ZR-FAE M 5DR CBI BENSIN	Norrbottns Bildemontering AB 0929-70000	19.650 A
4569 5076	W1064422 400 SEK	Toyota Avensis -10 Spolarpump Baklucka	TOYOTA AVENSIS 1AD-FTV M 5DR CBI DIESEL FÖR BAKRUTA	Norrbottns Bildemontering AB 0929-70000	23.501 A
1538 5076	W1060926 195 SEK	BMW 5-Series -03 Spolarpump Baklucka	BMW 525IA LIMOUSINE M54-B25 AUT 4DR SED BENSIN	Norrbottns Bildemontering AB 0929-70000	14.981 A
4581 5076	W1060658 195 SEK	Toyota RAV 4 -08 Spolarpump Baklucka	TOYOTA RAV 4 2AD-FTV M 5DR SUV DIESEL DENSO	Norrbottns Bildemontering AB 0929-70000	28.000 A
5060 5076	W1057743 125 SEK	Volvo 940 -95 Spolarpump Baklucka	VOLVO 945-811 S 2.3 B230FK M 5DR CBI BENSIN 5DRS BAKRE SVART KONTAKT	Norrbottns Bildemontering AB 0929-70000	35.147 A
4527 5076	W1037438 195 SEK	Toyota Yaris -10 Spolarpump Baklucka	TOYOTA YARIS 1NR-FE M 5DR CSE BENSIN	Norrbottns Bildemontering AB 0929-70000	17.061 A
5013 5076	W1034596 162 SEK	Volvo 240 -88 Spolarpump Baklucka	VOLVO 245 2.3i 5VXL 5DR CBI BENSIN SVART KONTAKT	Norrbottns Bildemontering AB 0929-70000	39.435 A
5050 5076	W1031825 125 SEK	Volvo 740 -88 Spolarpump Baklucka	VOLVO 745 GLE B230E T 5DR CBI BENSIN SVART KONTAKT	Norrbottns Bildemontering AB 0929-70000	22.603 A
4026 5076	W1026596 90 SEK	Saab 9-5 -10 Spolarpump Baklucka	SAAB 9-5 B205E/B A 5DR CBI ETANOL E85	Norrbottns Bildemontering AB 0929-70000	12.203 A
5013 5076	W1003468 162 SEK	Volvo 240 -90 Spolarpump Baklucka	VOLVO 245 2.3 MAN 2.3i 116HK 5VXL 5DR CBI BENSIN VIT/SVART KONTAKT VDO	Norrbottns Bildemontering AB 0929-70000	31.478 A
5060 5076	W1001245 125 SEK	Volvo 940 -94 Spolarpump Baklucka	VOLVO 945-833 GL B230FD M 5DR CBI BENSIN VDO SVART KONTAKT	Norrbottns Bildemontering AB 0929-70000	32.394 A
5060 5076	W1000847 125 SEK	Volvo 940 -96 Spolarpump Baklucka	VOLVO 945 B230FK M 5DR CBI BENSIN VDO SVART KONTAKT	Norrbottns Bildemontering AB 0929-70000	34.755 A
4555 5076	W995543 370 SEK	Toyota Yaris -19 Spolarpump Baklucka	TOYOTA YARIS HYBRID 1.5HYBRID AUT 5DR CSE ELHYBRID	Norrbottns Bildemontering AB 0929-70000	5.118 A
4037 5076	W992418 150 SEK	Saab 9-3 -11 Spolarpump Baklucka	SAAB 9-3 XWD 2.0T BIO 210HK 6VXL 4WD 5DR CBI ETANOL	Norrbottns Bildemontering AB 0929-70000	17.516 A
4572 5076	W992151 190 SEK	Toyota Avensis -00 Spolarpump Baklucka	TOYOTA AVENSIS 2.0i 150HK 5VXL 2.0 150HK 5VXL 5DR C BAKRUTA ROSA KONTAKT/SVART/VIT TEXTRON	Norrbottns Bildemontering AB 0929-70000	23.374 A
4568 5076	W991053 190 SEK	Toyota Avensis -08 Spolarpump Baklucka	TOYOTA AVENSIS 2.0 5VXL CBI 2.0 5VXL 5DR CBI BENSIN ROSA/SVART/VIT	Norrbottns Bildemontering AB 0929-70000	20.994 A
1516 5076	W982288 195 SEK	BMW X1 -12 Spolarpump Baklucka	BMW X1 XDRIVE 20D N47-D20C M 5DR SUV DIESEL	Norrbottns Bildemontering AB 0929-70000	17.293 A
5060 5076	W973560 125 SEK	Volvo 940 -96 Spolarpump Baklucka	VOLVO 945-811 S 2.3 2.3T 135HK 5VXL 5DR CBI BENSIN SVART KONTAKT	Norrbottns Bildemontering AB 0929-70000	27.777 A
4555 5076	W971335 370 SEK	Toyota Yaris -17 Spolarpump Baklucka	TOYOTA YARIS 1.5 112HK 6VXL 5DR CSE BENSIN	Norrbottns Bildemontering AB 0929-70000	4.008 A
5051 5076	W969211 125 SEK	Volvo 740 -92 Spolarpump Baklucka	VOLVO 745-883 GL/SE-PKT B230F M 5DR CBI BENSIN VDO SVART KONTAKT	Norrbottns Bildemontering AB 0929-70000	30.258 A
4477 5076	W963902 350 SEK	Suzuki Grand Vitara -08 Spolarpump Baklucka	GRAND VITARA 1.9DDIS 6VXL 4WD 1.9DDIS 95KW 6VXL 4WD MITSUBA	Norrbottns Bildemontering AB 0929-70000	19.001 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4477 5076	W963903 350 SEK	Suzuki Grand Vitara -08 Spolarpump Baklucka	GRAND VITARA 1.9DDIS 6VXL 4WD 1.9DDIS 95KW 6VXL 4WD MITSUBA	Norrbottens Bildemontering AB 0929-70000	19.001 A
4037 5076	W963779 150 SEK	Saab 9-3 -08 Spolarpump Baklucka	9-3 VECTOR 2,0T AUT CBI 2,0T 129KW AUT 5DR CBI ETAN	Norrbottens Bildemontering AB 0929-70000	24.656 A
4555 5076	W941474 395 SEK	Toyota Yaris -20 Spolarpump Baklucka	TOYOTA YARIS 1.5I 112HK AUT 5DR CSE BENSIN	Norrbottens Bildemontering AB 0929-70000	621 A
4555 5076	W931586 395 SEK	Toyota Yaris -19 Spolarpump Baklucka	TOYOTA YARIS HYBRID 1.5I HYBR 73HK AUT 5DR CSE ELHY	Norrbottens Bildemontering AB 0929-70000	1.127 A
4036 5076	W876363 212 SEK	Saab 9-3 -06 Spolarpump Baklucka	9-3 (II) 1.9TID R4 120HK 6VXL 5DR CBI DIESEL	Norrbottens Bildemontering AB 0929-70000	12.190 A
4528 5076	W863828 370 SEK	Toyota Yaris -14 Spolarpump Baklucka	TOYOTA YARIS 1.33I 99HK AUT 5DR CSE BENSIN	Norrbottens Bildemontering AB 0929-70000	6.702 A