

| BKod DKod | Lagernummer Pris | Fordon Del | Fordon Information Del Information | Företag Telefon | Mil Kvalité |
|--------------|-----------------------|---|--|--|----------------|
| 2454 5048 | W1075014 | Ford Kuga -18 Bakljus Baklucka Höger | FORD KUGA T8MA A 5DR SUV DIESEL VALEO | Norrbottns Bildemontering AB 0929-70000 | 11.183 A* |
| 4489 5048 | W1074796 | Toyota Corolla -23 Bakljus Baklucka Höger | TOYOTA COROLLA 2ZR-FXE V 5DR CBI ELHYBRID B | Norrbottns Bildemontering AB 0929-70000 | 8.239 A* |
| 1540 5048 | W1074295 | BMW 5-Series -14 Bakljus Baklucka Höger | BMW 520D XDRIVE N47-D20C A 5DR CBI DIESEL | Norrbottns Bildemontering AB 0929-70000 | 17.477 A* |
| 4490 5048 | W1074373 | Toyota RAV 4 -23 Bakljus Baklucka Höger | TOYOTA RAV4 VARIOMATIC SUV ELHYBRID ICHIKOH | Norrbottns Bildemontering AB 0929-70000 | 336 A* |
| 3503 5048 | W1073485 | Opel Insignia -19 Bakljus Baklucka Höger | OPEL INSIGNIA SPORTS TOURER B16DTE 5DR CBI DIESEL | Norrbottns Bildemontering AB 0929-70000 | 2.586 A* |
| 5095 5048 | W1073271 737 SEK | Volvo XC60 -23 Bakljus Baklucka Höger | VOLVO XC60 D420T8 A 5DR SUV ELHYBRID D | Norrbottns Bildemontering AB 0929-70000 | 1.650 A* |
| 3343 5048 | W1072915 | Mercedes E-Class 96->> -15 Bakljus Baklucka Höger | MERCEDES-BENZ 212 K E 220 CDI OM651.924 5DR CBI DIE | Norrbottns Bildemontering AB 0929-70000 | 14.323 A* |
| 5060 5048 | W1072674 750 SEK | Volvo 940 -91 Bakljus Baklucka Höger | VOLVO 944-852 GL B230FB T 4DR SED BENSIN SEDAN, VIT/RÖD, HELLA | Norrbottns Bildemontering AB 0929-70000 | 30.718 A* |
| 2173 5048 | W1072268 | Nissan Qashqai -16 Bakljus Baklucka Höger | NISSAN QASHQAI K9K M 5DR SUV DIESEL | Norrbottns Bildemontering AB 0929-70000 | 9.329 A* |
| 5046 5048 | W1072240 1.500 SEK | Volvo V90 Cross Country -21 Bakljus Baklucka Höger | VOLVO V90 CROSS COUNTRY D4204T14 A 5DR CBI DIESEL UTAN DIMBAKLJUS | Norrbottns Bildemontering AB 0929-70000 | 9.810 A* |
| 1712 5048 | W1072476 | Citroen C5 -17 Bakljus Baklucka Höger | CITROEN C5 AHW A 5DR CBI DIESEL | Norrbottns Bildemontering AB 0929-70000 | 10.682 A* |
| 1511 5048 | W1072022 | BMW X3 -12 Bakljus Baklucka Höger | BMW X3 XDRIVE 20D N47-D20C A 5DR SUV DIESEL | Norrbottns Bildemontering AB 0929-70000 | 29.879 A* |
| 5073 5048 | W1071765 587 SEK | Volvo S60 -12 Bakljus Baklucka Höger | VOLVO S60 D5 AWD D5244T15 A 4DR SED DIESEL | Norrbottns Bildemontering AB 0929-70000 | 5.805 A* |
| 5008 5048 | W1071665 587 SEK | Volvo S60 -16 Bakljus Baklucka Höger | VOLVO S60 D4204T14 A 4DR SED DIESEL | Norrbottns Bildemontering AB 0929-70000 | 11.286 A* |
| 5095 5048 | W1071273 737 SEK | Volvo XC60 -19 Bakljus Baklucka Höger | VOLVO XC60 D4204T14 A 5DR SUV DIESEL | Norrbottns Bildemontering AB 0929-70000 | 17.425 A* |
| 4596 5048 | W1071176 | Toyota Auris -14 Bakljus Baklucka Höger | TOYOTA AURIS 2ZR-FXE V 5DR CBI ELHYBRID B KOMBI | Norrbottns Bildemontering AB 0929-70000 | 16.735 A* |
| 2732 5048 | W1070889 | Honda Civic -17 Bakljus Baklucka Höger | HONDA CIVIC 4DR L15B7 V 4DR SED BENSIN | Norrbottns Bildemontering AB 0929-70000 | 6.012 M |
| 4489 5048 | W1071027 | Toyota Corolla -20 Bakljus Baklucka Höger | TOYOTA COROLLA 2ZR-FXE V 5DR CBI ELHYBRID B | Norrbottns Bildemontering AB 0929-70000 | 34.651 M |
| 2708 5048 | W1070687 1.025 SEK | Honda Accord -09 Bakljus Baklucka Höger | HONDA ACCORD N22B1 M 5DR CBI DIESEL KOMBI | Norrbottns Bildemontering AB 0929-70000 | 25.407 A* |
| 2473 5048 | W1070527 | Ford Focus -12 Bakljus Baklucka Höger | FORD FOCUS T3DB M 5DR CBI DIESEL KOMBI | Norrbottns Bildemontering AB 0929-70000 | 16.891 A* |
| 4402 5048 | W1070566 | Suzuki Ignis -18 Bakljus Baklucka Höger | SUZUKI IGNIS K12C A 5DR CBI BENSIN | Norrbottns Bildemontering AB 0929-70000 | 2.115 A* |
| 3228 5048 | W1070497 | Mazda 6 -17 Bakljus Baklucka Höger | MAZDA 6 SH A 5DR CBI DIESEL | Norrbottns Bildemontering AB 0929-70000 | 17.671 A* |
| 4490 5048 | W1070489 | Toyota RAV 4 -23 Bakljus Baklucka Höger | TOYOTA RAV 4 A25A-FXS V SUV ICHIKOH | Norrbottns Bildemontering AB 0929-70000 | - A* |
| 4929 5048 | W1069793 | VW Passat -13 Bakljus Baklucka Höger | VOLKSWAGEN PASSAT CFFB M 5DR CBI DIESEL | Norrbottns Bildemontering AB 0929-70000 | 16.059 A* |

| BKod DKod | Lagernummer Pris | Fordon Del | Fordon Information Del Information | Företag Telefon | Mil Kvalité |
|--------------|---------------------|--|---|---|----------------|
| 3245 5048 | W1069299 975 SEK | Mazda CX-5 -18 Bakljus Baklucka Höger | MAZDA CX-5 SH-VPTS A 5DR SUV DIESEL | Norrbottens Bildemontering AB 0929-70000 | 10.531 A* |
| 4555 5048 | W1068890 | Toyota Yaris -20 Bakljus Baklucka Höger | TOYOTA YARIS 2NR-FKE M 5DR CSE BENSIN | Norrbottens Bildemontering AB 0929-70000 | 1.976 A* |
| 3343 5048 | W1068679 | Mercedes E-Class 96->> -14 Bakljus Baklucka Höger | MERCEDES-BENZ 212 K E 220 CDI OM651.924 5DR CBI DIE | Norrbottens Bildemontering AB 0929-70000 | 44.187 M |
| 3244 5048 | W1068342 445 SEK | Mazda CX-5 -14 Bakljus Baklucka Höger | MAZDA CX-5 IPM, 2.2 DE 2.2 MZR-CD AUT 4WD 5DR SUV D | Norrbottens Bildemontering AB 0929-70000 | 20.587 M |
| 2729 5048 | W1068176 470 SEK | Honda Civic -08 Bakljus Baklucka Höger | HONDA CIVIC 5DR R18A2 A 5DR CSE BENSIN KOITO | Norrbottens Bildemontering AB 0929-70000 | 17.239 A* |
| 1532 5048 | W1068053 995 SEK | BMW 3-Series -18 Bakljus Baklucka Höger | BMW 320D XDRIVE B47-D20A A 5DR CSE DIESEL | Norrbottens Bildemontering AB 0929-70000 | 13.282 A* |