

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
1336 7645	W732242 750 SEK	Audi A6 / S6, A6 E-Tron -96 ABS Hydraulaggregat	2,6l AVANT 2,6l/ABC 5VXL/CPE 5DR HGV BENSIN	Vimmerby Bildmontering AB 0492-20028	21.924 A
4024 7645	W717501 500 SEK	Saab 9-5 -02 ABS Hydraulaggregat	LINEAR 150HK 2,0T/B205E 5VXL 4DR SED BENSIN 0273004223 TESTAD, OK 0273004223	Vimmerby Bildmontering AB 0492-20028	21.296 A
5070 7645	W640777 1.000 SEK	Volvo S40, V40 96-04 -98 ABS Hydraulaggregat	1,6l 16V 1,6l/B4164S 5VXL 5DR CBI BENSIN	Vimmerby Bildmontering AB 0492-20028	23.385 A
2429 7645	W430291 2.000 SEK	Ford C-MAX, Ford Focus C-MAX -04 ABS Hydraulaggregat	C-MAX 1,8l 120HK 1,8l/CSDA 5VXL 5DR HGV BENSIN TESTAD, OK! (ENDAST BLOCK) , 2050	Vimmerby Bildmontering AB 0492-20028	18.530 A
4926 7645	W299773 1.250 SEK	VW Passat -98 ABS Hydraulaggregat	1,9TDI 110HK 1,9TDI/AFN 5VXL/DHF 5DR HGV DIESEL 1,9TDI 1,9TDI	Vimmerby Bildmontering AB 0492-20028	38.404 A
4202 7645	W244586 1.000 SEK	Skoda Octavia -03 ABS Hydraulaggregat	1,6l 8V 102HK CC-KAROSS 1,6l/BFQ 5VXL/DUU 5DR CC BE	Vimmerby Bildmontering AB 0492-20028	16.650 A
5511 7645	W241948 3.000 SEK	Ssang Yong Actyon / Sport -07 ABS Hydraulaggregat	2,0XDI 4WD 141HK SUV 2,0XDI/D20D051 5VXL 4WD 5DR SU	Vimmerby Bildmontering AB 0492-20028	7.024 A
3493 7645	W241646 3.000 SEK	Mitsubishi L200 -06 ABS Hydraulaggregat	2,5TD 116HK 4DR PICKUP 2,5TD/4D56 AUTOMAT 4DR PIC D	Vimmerby Bildmontering AB 0492-20028	5.734 A
5065 7645	W241280 1.000 SEK	Volvo 960 -93 ABS Hydraulaggregat	3,0l 204HK SEDAN 3,0l/B6304F AUTOMAT/TILLSAT 4DR SE	Vimmerby Bildmontering AB 0492-20028	18.623 A
4507 7645	W240026 1.000 SEK	Toyota Camry -93 ABS Hydraulaggregat	2,2l 16V 2,2l/5S-FE MANUELL 4DR SED BENSIN	Vimmerby Bildmontering AB 0492-20028	18.421 A
4036 7645	W229426 1.000 SEK	Saab 9-3 -06 ABS Hydraulaggregat	2,0T VECTOR SPORTCOMBI 2,0T/B207L 5VXL/FM55101 5DR	Vimmerby Bildmontering AB 0492-20028	14.820 A
3628 7645	W216967 2.500 SEK	Peugeot 307 -05 ABS Hydraulaggregat	1,6l 109HK 1,6l/NFU 5VXL 5DR CBI BENSIN	Vimmerby Bildmontering AB 0492-20028	14.566 A
3843 7645	W220164 2.000 SEK	Renault Megane -03 ABS Hydraulaggregat	1,6l 16V 1,6l/K4MT7/60 5VXL 5DR CC BENSIN	Vimmerby Bildmontering AB 0492-20028	10.590 A
5070 7645	W218183 250 SEK	Volvo S40, V40 96-04 -96 ABS Hydraulaggregat	2,0l 16V 136HK 2,0l/B4204S 5VXL 4DR SED BENSIN	Vimmerby Bildmontering AB 0492-20028	20.457 A
3641 7645	W217988 1.000 SEK	Peugeot 406 -03 ABS Hydraulaggregat	2,0HDI 109HK KOMBI 2,0HDI/RHZ 5VXL 5DR CBI DIESEL	Vimmerby Bildmontering AB 0492-20028	24.975 A
5511 7645	W215075 3.000 SEK	Ssang Yong Actyon / Sport -08 ABS Hydraulaggregat	2,0XDI 2,0XDI/D20D051 AUTOMAT 4DR PIC DIESEL	Vimmerby Bildmontering AB 0492-20028	4.998 A
3526 7645	W212295 500 SEK	Opel Astra -99 ABS Hydraulaggregat	1,6l 101HK 1,6l/X16XEL 5VXL 5DR CBI BENSIN	Vimmerby Bildmontering AB 0492-20028	24.335 A
4514 7645	W206505 700 SEK	Toyota Carina -96 ABS Hydraulaggregat	2,0l 2,0l/3S-FE 5VXL 4DR SED BENSIN 8+4STIFT	Vimmerby Bildmontering AB 0492-20028	26.601 A
5070 7645	W205099 250 SEK	Volvo S40, V40 96-04 -96 ABS Hydraulaggregat	2,0l 16V 2,0l/B4204S 5VXL 4DR SED BENSIN	Vimmerby Bildmontering AB 0492-20028	22.435 A
3641 7645	W202432 1.000 SEK	Peugeot 406 -01 ABS Hydraulaggregat	2,0HDI 109HK 2,0HDI/RHZ 5VXL 5DR HGV DIESEL	Vimmerby Bildmontering AB 0492-20028	24.773 A
3560 7645	W202343 500 SEK	Opel Zafira -99 ABS Hydraulaggregat	1,6l 16V 101HK 1,6l/X16XEL 5VXL 5DR BUS BENSIN	Vimmerby Bildmontering AB 0492-20028	20.366 A
3842 7645	W201562 2.000 SEK	Renault Megane -99 ABS Hydraulaggregat	1,6l 16V KOMBI 107HK 1,6l/K4M700 5VXL 5DR CBI BENSIN	Vimmerby Bildmontering AB 0492-20028	18.862 A
4514 7645	W201366 800 SEK	Toyota Carina -98 ABS Hydraulaggregat	1,8l 107HK 1,8l/7A-FE 5VXL 5DR CC BENSIN 8+4STIFT	Vimmerby Bildmontering AB 0492-20028	25.781 A
3332 7645	W200282 1.500 SEK	Mercedes C-Class -98 ABS Hydraulaggregat	2,2CDI 2,2CDI/OM611960 AUTOMAT 5DR CBI DIESEL	Vimmerby Bildmontering AB 0492-20028	41.334 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
4036 7645	W199747 1.000 SEK	Saab 9-3 -03 ABS Hydraulaggregat	1,8T 150HK 1,8T/B207E 5VXL 4DR SED BENSIN	Vimmerby Bildemontering AB 0492-20028	10.041 A
3542 7645	W199501 1.000 SEK	Opel Omega -99 ABS Hydraulaggregat	2,0DTI 2,0DTI/X20DTH 5VXL 5DR CBI DIESEL	Vimmerby Bildemontering AB 0492-20028	25.349 A
3882 7645	W196499 1.000 SEK	Renault Kangoo -04 ABS Hydraulaggregat	1,6l 16V VÄNSTERSTYRD POSTBIL 1,6l/7700203 AUTOMAT POSTBIL (8200229137 POSTBIL (8200229137	Vimmerby Bildemontering AB 0492-20028	14.700 A
3332 7645	W191611 1.500 SEK	Mercedes C-Class -94 ABS Hydraulaggregat	2,2 BENSIN 2,2l/M111961 5VXL 4DR SED BENSIN	Vimmerby Bildemontering AB 0492-20028	19.942 A
1722 7645	W190576 1.000 SEK	Citroen Xsara -02 ABS Hydraulaggregat	1,6l 16V 1,6l/NFU 5VXL 5DR HGV BENSIN	Vimmerby Bildemontering AB 0492-20028	14.076 A
3616 7645	W188686 800 SEK	Peugeot 206 -01 ABS Hydraulaggregat	2,0GTI 2,0l/RFN 5VXL 3DR CC BENSIN	Vimmerby Bildemontering AB 0492-20028	14.518 A