

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
1540 5077	W582635 250 SEK	BMW 5-Series -13 Bakrute torkarmekanism Bak	BMW 530 D WAGON 5-DOOR N47-D20C AUTOMAT 5DR KOMBI	Alingsås Bildelar AB 0322-10527	21.750 A
1540 5077	W579546 300 SEK	BMW 5-Series -11 Bakrute torkarmekanism Bak	BMW 5K 535D N57-D30B AUTOMAT 5DR KOMBI DIESEL	Alingsås Bildelar AB 0322-10527	19.995 A
2174 5077	W572676 200 SEK	Nissan Qashqai -13 Bakrute torkarmekanism Bak	NISSAN J10 NISSAN QASHQAI MR20DE V 5DR SUV BENSIN BAK, BOSCH	Alingsås Bildelar AB 0322-10527	13.744 A
1540 5077	W514828 300 SEK	BMW 5-Series -11 Bakrute torkarmekanism Bak	BMW 530 D KOMBI 5D N47-D20C AUTOMAT 5DR KOMBI DIES	Alingsås Bildelar AB 0322-10527	31.552 A
3842 5077	W415033 300 SEK	Renault Megane -02 Bakrute torkarmekanism Bak	5DCS 1,6i16V 5VXL SER ABS 1,6i16V 5-MANUELL 5DR KO KOMPL UTAN MOTOR	Alingsås Bildelar AB 0322-10527	14.232 A
5012 5077	W29359 140 SEK	Volvo 240 -88 Bakrute torkarmekanism Bak		Alingsås Bildelar AB 0322-10527	- M
5055 5077	W171857 400 SEK	Volvo 850 -94 Bakrute torkarmekanism Bak	5DCBI B5252S 5VXL SER ABS B5252S 5-MANUELL 5DR CBI KOMPL UTAN MOTOR	Alingsås Bildelar AB 0322-10527	40.307 A
5055 5077	W67548 350 SEK	Volvo 850 -94 Bakrute torkarmekanism Bak	5DCBI B5252S 5VXL SER ABS B5252S MED PUMP 5VXL 3397020490 BOSCH	Alingsås Bildelar AB 0322-10527	34.850 M
5013 5077	W28030 200 SEK	Volvo 240 -88 Bakrute torkarmekanism Bak	5D KOMBI GL 5VXL KAT SERV B230F 5VXL M47 MED SPINDEL & STAG	Alingsås Bildelar AB 0322-10527	23.654 A