

| BKod DKod | Lagernummer Pris | Fordon Del | Fordon Information Del Information | Företag Telefon | Mil Kvalité |
|--------------|-----------------------|---|--|--|----------------|
| 3334 8026 | W55892 400 SEK | Mercedes C-Class -11 Cirkulationspump | AUT 1,8 B.E. 4D HGV GRÅ 1,8 115KW M271. AUT CBI | Gäresta Bildelar AB 0457-36033 | 6.084 A |
| 4937 8026 | W661045 495 SEK | VW Polo -14 Cirkulationspump | , VW 6R POLO CBZC MANUELL 5DR KOMBI-SEDAN BENSIN | Växjö Bildemontering AB 0470-709650 | 10.154 A |
| 4972 8026 | W637638 625 SEK | VW Caddy -20 Cirkulationspump | 5DMAXI 2,0TDI AUT ABS 3 STIFT | Svensk Biläterving AB 019-450690 | 7.246 A |
| 1323 8026 | W41291 200 SEK | Audi A4, S4 -12 Cirkulationspump | 2.0 TDI DIESEL AVANT 143 CJCA | Nybro Bildemontering AB 0481-66000 | 23.000 A |
| 4972 8026 | W637639 625 SEK | VW Caddy -20 Cirkulationspump | 5DMAXI 2,0TDI AUT ABS 3 STIFT | Svensk Biläterving AB 019-450690 | 7.246 A |
| 5576 8026 | W638005 | KIA Cee'd, Cee'd SW -23 Cirkulationspump | KIA CEED / CEED SW 19-8qjt> G4LE AUTOMAT 5DR STATIONS | Autodemontering TT AB 0416-511370 | 528 A |
| 1533 8026 | W1349550 375 SEK | BMW 3-Series -21 Cirkulationspump | BMW 330E G21 SPORT LINE 19- 330E B48-B20A AUTO | Upplands Bildemontering AB 018-169225 | 2.229 A |
| 5576 8026 | W638006 | KIA Cee'd, Cee'd SW -23 Cirkulationspump | KIA CEED / CEED SW 19-8qjt> G4LE AUTOMAT 5DR STATIONS | Autodemontering TT AB 0416-511370 | 528 A |
| 1323 8026 | W41290 275 SEK | Audi A4, S4 -12 Cirkulationspump | 2.0 TDI DIESEL AVANT 143 CJCA | Nybro Bildemontering AB 0481-66000 | 23.000 A |
| 4943 8026 | W602599 375 SEK | VW Crafter, e-Crafter -19 Cirkulationspump | , VW VW CRAFTER AUT DAVA AUTOMAT 0DR FLAKVCHASSID | Frykmalm i Karlstad AB 054-856420 | 30.542 A |
| 1371 8026 | W416605 1.786 SEK | Audi Q4 e-tron -23 Cirkulationspump | AUDI Q4 50 E TRON FZ BM9T AUTOMAT VANNPUMPE | | 1.356 A |
| 3232 8026 | W2620266 2.250 SEK | Mazda CX-60 -23 Cirkulationspump | MAZDA CX-60 4D 2,5PHEV COMBI AWD PY, 2,5PHEV AUT BOSCH | Atracco AB - Växjö 0470-771120 | 648 A |
| 4972 8026 | W1282015 | VW Caddy -16 Cirkulationspump | CADDY 16-20 DFSF MANUELL 5DR SKÅPBIL DIESEL | Walters Bildelar AB 0346-714580 | 13.197 A |
| 3232 8026 | W2620267 625 SEK | Mazda CX-60 -23 Cirkulationspump | MAZDA CX-60 4D 2,5PHEV COMBI AWD PY, 2,5PHEV AUT VENTIL | Atracco AB - Växjö 0470-771120 | 648 A |
| 1371 8026 | W416603 1.786 SEK | Audi Q4 e-tron -23 Cirkulationspump | AUDI Q4 50 E TRON FZ BM9T AUTOMAT VANNPUMPE | | 1.356 A |
| 5032 8026 | W1737105 637 SEK | Volvo V60 -20 Cirkulationspump | VOLVO V60 D3 2,0 D4204T4 TRONIC 5DR CBI DIESEL | Ådalens Bildemontering AB 0612-12420 | 14.776 A |
| 3232 8026 | W618193 2.250 SEK | Mazda CX-60 -23 Cirkulationspump | CX-60 AUTOMAT 5DR SUV ELHYBRID BENSIN | Lycksele Bildemontering AB 0950-12140 | - A |
| 4951 8026 | W416867 491 SEK | VW Passat -16 Cirkulationspump | PASSAT 3C GTE 1.4 HYBRID AUTOMAT 2VD 5DR ELHYBRID B | | 12.452 A |
| 3298 8026 | W1349326 1.100 SEK | Mercedes A-Class -19 Cirkulationspump | MB A200 AMG-SPORT (W177) 18- A200 282914 AUT | Upplands Bildemontering AB 018-169225 | 2.949 A |
| 3232 8026 | W618168 8.750 SEK | Mazda CX-60 -23 Cirkulationspump | CX-60 AUTOMAT 5DR SUV ELHYBRID BENSIN VÄRMARE PHEV BATTERI | Lycksele Bildemontering AB 0950-12140 | - A |
| 4908 8026 | W41321 175 SEK | VW Golf, e-Golf -11 Cirkulationspump | 1.4 TSI KOMBI-SEDAN 122 H CAXA | Nybro Bildemontering AB 0481-66000 | - A |
| 4673 8026 | W1281797 | Toyota Yaris Cross -22 Cirkulationspump | YARIS CROSS 21-8qjt> M15A-FXE AUTOMAT 5DR HALV KOMBI E OSPECIFICERAT | Walters Bildelar AB 0346-714580 | 1.679 A |
| 3232 8026 | W618218 500 SEK | Mazda CX-60 -23 Cirkulationspump | CX-60 AUTOMAT 5DR SUV ELHYBRID BENSIN VENTIL | Lycksele Bildemontering AB 0950-12140 | - A |
| 3232 8026 | W618219 500 SEK | Mazda CX-60 -23 Cirkulationspump | CX-60 AUTOMAT 5DR SUV ELHYBRID BENSIN VENTIL | Lycksele Bildemontering AB 0950-12140 | - A |

| BKod DKod | Lagernummer Pris | Fordon Del | Fordon Information Del Information | Företag Telefon | Mil Kvalité |
|--------------|----------------------|---|--|---|----------------|
| 2202 8026 | W886829 | Fiat 500 -16 Cirkulationspump | E SMG 180/120 E SMG 180/120 2WD 3DR KBI EL | Østfold bildemontering AS (0047) -69127222 | 5.000 A |
| 4489 8026 | W1074826 | Toyota Corolla -23 Cirkulationspump | TOYOTA COROLLA 2ZR-FXE V 5DR CBI ELHYBRID B AISIN | Norrbottnens Bildemontering AB 0929-70000 | 8.239 A |
| 4956 8026 | W637369 500 SEK | VW Golf Sportsvan -18 Cirkulationspump | 5DK-S 1,2TSI AUT ABSESP 3 STIFT | Svensk Bilåtervinning AB 019-450690 | 3.516 A |
| 4951 8026 | W416419 1.488 SEK | VW Passat -16 Cirkulationspump | PASSAT 3C GTE 1.4 HYBRID AUTOMAT 2WD 5DR ELHYBRID B | | 12.452 A |
| 3692 8026 | W660656 | Peugeot Partner -19 Cirkulationspump | PEUGEOT PARTNER KORT SKÅP 2+1+1D YHZ AUTOMAT 5DR M | Växjö Bildemontering AB 0470-709650 | 12.987 A |
| 5032 8026 | W637242 700 SEK | Volvo V60 -20 Cirkulationspump | 5DCBI 2,0D3 AUT ABS ESPPDC NAV LED BLIS EXTRA VATTENPUMP, 3 STIFT | Svensk Bilåtervinning AB 019-450690 | 10.877 A |