

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
1760 5013	W743097	Citroen C1 -07 Baklucka CC / Kombi-Sedan	CITROEN C1 RUTA	Södertälje Bil och Alldemo AB 08-55096165	19.995 A
4944 5013	W450449 5.456 SEK	VW UP!, E-UP! -17 Baklucka CC / Kombi-Sedan	UP! AA 1.0 CHYA MANUELL 2WD 5DR BENSIN 2011-/ KOMPLETT	Møre Bruktbildeler A/S (0047) 70-272700	6.321 A
3632 5013	W1349107 4.995 SEK	Peugeot 308 -17 Baklucka CC / Kombi-Sedan Bak	PEUGEOT 308 1,6 BLUEHDI 14-21 1,6 HDI BHZ AU	Upplands Bildemontering AB 018-169225	6.588 A
2163 5013	W886508	Nissan Leaf -14 Baklucka CC / Kombi-Sedan	EV EM57 EV EM57 AUTOMAT 2WD 5DR KBI EL	Østfold bildemontering AS (0047) -69127222	12.100 A
3632 5013	W660429	Peugeot 308 -14 Baklucka CC / Kombi-Sedan Bak	PEUGEOT 308 ACCESSIACTIVE KOMBI 5D 5FA MANUELL 5DR	Växjö Bildemontering AB 0470-709650	8.265 M
5442 5013	W60189 3.000 SEK	Ligier JS 50 -16 Baklucka CC / Kombi-Sedan	3DR CC 492DCI AUTO UTAN BROMLJUS	Ericssons Bildemontering AB 0370-28100	1.764 A
4430 5013	W24530 1.500 SEK	Suzuki Splash -09 Baklucka CC / Kombi-Sedan	1.0I-12V KOMBI-SEDAN	Nya Angeredes Bildelar AB 031-3301120	21.396 A
1345 5013	W1003312 2.500 SEK	Audi A3, S3 -12 Baklucka CC / Kombi-Sedan Bak	AUDI A3 TDI KOMBI-SEDAN 5D CFFB MANUELL 5DR KOMBI BUCKLA, LITE VEKEN I HÖRN 60P	Atracco AB - Mönsterås 0499-49000	21.191 M
3617 5013	W44022 1.500 SEK	Peugeot 207 -07 Baklucka CC / Kombi-Sedan	PEUGEOT 207 1,6 HDI 9HZ M 5DR DIESEL	Eskilstuna Bildemontering AB 016-139906	21.414 A*
5217 5013	W886422	Hyundai Kona / Electric -20 Baklucka CC / Kombi-Sedan	ELECTRIC EM16 ELECTRIC EM16 AUTOMAT 2WD 5DR SUV EL	Østfold bildemontering AS (0047) -69127222	4.400 A
3826 5013	W715659 2.750 SEK	Renault Clio -15 Baklucka CC / Kombi-Sedan Bak	CLIO IV 1.2 TCE H5F-403 AUTOMAT 5DR HALVKOMBI BENS	Häggs Bildemontering i Ilsbo AB 0652-565000	3.785 A*
5575 5013	W43938 2.800 SEK	KIA Cee'd, Cee'd SW -09 Baklucka CC / Kombi-Sedan	1.6 CRDI D4FB-L MAN 5 VÅXELL 5DR DIESEL BRUKSSKICK	Eskilstuna Bildemontering AB 016-139906	18.149 A
4953 5013	W886235 4.960 SEK	VW Polo -18 Baklucka CC / Kombi-Sedan	1.0 TSI CHZL 1.0 TSI CHZL MANUELL 2WD 5DR KBI BENSIN	Østfold bildemontering AS (0047) -69127222	9.434 A
4250 5013	W808610 4.375 SEK	Tesla Model S -15 Baklucka CC / Kombi-Sedan Bak	TESLA MODEL S 13- > L1S 5DR HALVKOMBI EL LITEN LACKSKADA	Kungsåra Bildemontering AB 021-4711100	13.000 A*
4546 5013	W108839 2.312 SEK	Toyota Prius -05 Baklucka CC / Kombi-Sedan Bak	TOYOTA PRIUS KOMBI-SEDAN 5D 1NZ-FXE V 5DR KOMBI-SE BAK	Sundsvalls Bildemontering AB 060-537890	26.290 A
2203 5013	W1510191 2.379 SEK	Fiat 500L -13 Baklucka CC / Kombi-Sedan Bak	1,4 I. FIAT 500 POP STAR 843.A1.000 / MAN 5DR KOMB BAK MED RUTA. 2ST SKADOR + EN BULA	Örebro Bildemontering AB 019-6701200	11.449 M
3515 5013	W617853	Opel Corsa -16 Baklucka CC / Kombi-Sedan Bak	CORSA-E B14XEL 5DR KOMBI-SEDAN BENSIN BAK	Lycksele Bildemontering AB 0950-12140	16.275 A
5279 5013	W2619939 4.500 SEK	Hyundai i10 -17 Baklucka CC / Kombi-Sedan Bak	HYUNDAI I10 5D 1,0 G3LA 1,0 MANUELL 5DR KOMBI-SEDA	Atracco AB - Växjö 0470-771120	3.876 A
5217 5013	W886179	Hyundai Kona / Electric -20 Baklucka CC / Kombi-Sedan	ELECTRIC EM ELECTRIC EM AUTOMAT 2WD 5DR SUV EL	Østfold bildemontering AS (0047) -69127222	10.127 A
5562 5013	W615624 2.500 SEK	KIA Venga -11 Baklucka CC / Kombi-Sedan Bak	KIA VENGA 1.6 KOMBI-SEDAN 5D G4FA MANUELL 5DR MINI	Alingsås Bildelar AB 0322-10527	4.909 A
4937 5013	W1281306	VW Polo -13 Baklucka CC / Kombi-Sedan Bak	POLO V (6R) 10-17 CBZC MANUELL 5DR HALVKOMBI BENSIN BAK	Walters Bildelar AB 0346-714580	9.739 A
3826 5013	W886261 3.968 SEK	Renault Clio -14 Baklucka CC / Kombi-Sedan	1.5 DCI K9K-608 1.5 DCI K9K-608 MANUELL 2WD 5DR KBI	Østfold bildemontering AS (0047) -69127222	20.390 A
1540 5013	W660358	BMW 5-Series -12 Baklucka CC / Kombi-Sedan Bak	BMW 5 F10F11/F18 09-17 N47-D20C AUTOMAT 4DR SEDAN	Växjö Bildemontering AB 0470-709650	24.969 M
5596 5013	W886213	KIA Soul -21 Baklucka CC / Kombi-Sedan	PSEV EM16 PSEV EM16 AUTOMAT 2WD 5DR KBI EL	Østfold bildemontering AS (0047) -69127222	3.000 A*

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
1512 5013	W450186 7.440 SEK	BMW X4 -15 Baklucka CC / Kombi-Sedan	X4 XDRIVE20D X3 20D B47-D20A AUTOMAT 4WD 5DR DIESEL 14-18	Møre Bruktbildeler A/S (0047) 70-272700	16.637 M
3228 5013	W886084	Mazda 6 -17 Baklucka CC / Kombi-Sedan	2.2 D SH 2.2 D SH AUTOMAT 2WD 5DR STV DIESEL	Østfold bildemontering AS (0047) -69127222	21.512 A
5314 5013	W99062 2.000 SEK	Seat Ibiza -11 Baklucka CC / Kombi-Sedan	SEAT 6J IBIZA CBZB M 5DR BENSIN	Hedin Recycled Halmstad AB 035-103232	24.730 A
1721 5013	W886009 7.440 SEK	Citroen DS5 -14 Baklucka CC / Kombi-Sedan	2.0 HDI RHH 2.0 HDI RHH AUTOMAT 2WD 5DR KBI DIESEL	Østfold bildemontering AS (0047) -69127222	21.647 A*
4553 5013	W101681 1.499 SEK	Toyota Corolla -02 Baklucka CC / Kombi-Sedan		Beg Bildelar Kolbäck AB 0220-41714	- A*
2538 5013	W660120	Chevrolet Captiva -11 Baklucka CC / Kombi-Sedan Bak	CHEVROLET CAPTIVA D KOMBI 5D A22DMH 5DR SUV DIESEL	Växjö Bildemontering AB 0470-709650	21.798 M