

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
3612 5076	W67938801	Peugeot 108 -15 Spolarpump Baklucka		AB Svenssons Bildemontering 044-244117	7.003 A
4527 5076	W602535 500 SEK	Toyota Yaris -11 Spolarpump Baklucka	TOYOTA YARIS 08-11 1KR-FE MANUELL 5DR FORDON AVSET	Frykmalm i Karlstad AB 054-856420	6.782 A
2327 5076	W743401	Ford Galaxy -14 Spolarpump Baklucka	FORD WA6 GALAXY	Södertälje Bil och Alldemo AB 08-55096165	19.564 A
4409 5076	W2523141 105 SEK	Suzuki SX4 -13 Spolarpump Baklucka	SX4 M16A MANUELL 5DR HALVKOMBI BENSIN	Eklunds Bildelslager i Skövde AB 0500-413845	9.018 A
3446 5076	W14920 150 SEK	Mitsubishi Outlander -03 Spolarpump Baklucka	2.4I-16V 4WD SUV 160 HK 4G69	Nybro Bildemontering AB 0481-66000	- A
1529 5076	W415625 99 SEK	BMW 3-Series -10 Spolarpump Baklucka	316D 3K 316D MK2 N47-D2 MANUELL 2WD 5DR DIESEL		22.781 A
1540 5076	W1074305	BMW 5-Series -14 Spolarpump Baklucka	BMW 520D XDRIVE N47-D20C A 5DR CBI DIESEL	Norrbottens Bildemontering AB 0929-70000	17.477 A
5081 5076	W602107 100 SEK	Volvo XC70 -00 Spolarpump Baklucka	VOLVO XC70 01-04 B5244T3 MANUELL 5DR BENSIN	Frykmalm i Karlstad AB 054-856420	23.991 A
5081 5076	W742814	Volvo XC70 -02 Spolarpump Baklucka	2.5 T	Södertälje Bil och Alldemo AB 08-55096165	20.347 A
1540 5076	W2521724 115 SEK	BMW 5-Series -13 Spolarpump Baklucka	F11 N47-D20C MANUELL 5DR KOMBI DIESEL CONTINENTAL	Eklunds Bildelslager i Skövde AB 0500-413845	21.864 A
4037 5076	W2521163 160 SEK	Saab 9-3 -10 Spolarpump Baklucka	9-3 FACELIFT B207E/B MANUELL 5DR KOMBI ETANOL E85	Eklunds Bildelslager i Skövde AB 0500-413845	23.868 A
1531 5076	W2521053 165 SEK	BMW 3-Series -14 Spolarpump Baklucka	3-SERIE D KOMBI 5D N47-D20C AUTOMAT 5DR KOMBI DIES	Eklunds Bildelslager i Skövde AB 0500-413845	26.087 A
4037 5076	W40679 150 SEK	Saab 9-3 -08 Spolarpump Baklucka	1.8 TURBO BIOPOWER KOMBI B207L	Nybro Bildemontering AB 0481-66000	- A
5599 5076	W1507930 230 SEK	KIA Sportage -15 Spolarpump Baklucka	1,6 GDI. KIA SPORTAGE R66K / G4FDF2973334 ZG77 /	Örebro Bildemontering AB 019-6701200	11.583 A
5081 5076	W601528 100 SEK	Volvo XC70 -04 Spolarpump Baklucka	VOLVO XC70 01-04 B5254T2 AUTOMAT 5DR STATIONSVAGN	Frykmalm i Karlstad AB 054-856420	36.106 A
1511 5076	W1071609	BMW X3 -12 Spolarpump Baklucka	BMW X3 XDRIVE 20D N47-D20C A 5DR SUV DIESEL	Norrbottens Bildemontering AB 0929-70000	29.879 A
1516 5076	W410441 243 SEK	BMW X1 -11 Spolarpump Baklucka	X1 XDRIVE18D X1 18D N47-D20C AUTOMAT 4WD 5DR DIESEL		26.667 A
1529 5076	W58809 200 SEK	BMW 3-Series -12 Spolarpump Baklucka	BMW 3K 320D XDRIVE N47-D20C A 5DR DIESEL	Skellefteå Bildemontering AB 0910-86122	16.642 A
1522 5076	W410610 243 SEK	BMW 1-Series -13 Spolarpump Baklucka	116D 1K4 116D MK1 N47-D2 AUTOMAT 2WD 5DR DIESEL		13.808 A
4411 5076	W1000126 175 SEK	Suzuki SX4 S-Cross -17 Spolarpump Baklucka	SUZUKI SX4 S-CROSS KOMBI 5D 2017- K14C AUTOMAT 5DR	Atracco AB - Mönsterås 0499-49000	3.283 A
4036 5076	W2519593 160 SEK	Saab 9-3 -06 Spolarpump Baklucka	9-3 B284L MANUELL 5DR KOMBI BENSIN 2 STIFT	Eklunds Bildelslager i Skövde AB 0500-413845	23.912 A
5599 5076	W2700698 250 SEK	KIA Sportage -15 Spolarpump Baklucka	KIA SPORTAGE KOMBI 5D D4FD 5DR SUV DIESEL	Atracco AB - Hedemora 0225-595540	24.019 A
1321 5076	W136201	Audi A4, S4 -07 Spolarpump Baklucka		AAA Bildemontering i Skutskär AB 026-79100	17.345 A
4573 5076	W1125456 120 SEK	Toyota Avensis -03 Spolarpump Baklucka	TOYOTA AVENSIS 03-06 1AZ-FSE AUTOMAT 5DR KOMBI BEN	Karstorps Bildemontering AB 011-4954000	32.777 A

BKod DKod	Lagernummer Pris	Fordon Del	Fordon Information Del Information	Företag Telefon	Mil Kvalité
5063 5076	W133698	Volvo V70 -11 Spolarpump Baklucka		AAA Bildemontering i Skutskär AB 026-79100	28.618 A
3837 5076	W130512	Renault Clio -08 Spolarpump Baklucka		AAA Bildemontering i Skutskär AB 026-79100	24.412 A
1540 5076	W1188669 146 SEK	BMW 5-Series -16 Spolarpump Baklucka	BMW 520D XDRIVE B47-D20A AUTOMAT 5DR CBI DIESEL	Allbildelar i Huddinge AB 010-4974200	19.362 A
4026 5076	W2518100 185 SEK	Saab 9-5 -08 Spolarpump Baklucka	9-5 B205E AUTOMAT 5DR STATIONSVAGN KOMBIVAGN BENSI	Eklunds Bildelslager i Skövde AB 0500-413845	26.228 A
4555 5076	W635630 325 SEK	Toyota Yaris -19 Spolarpump Baklucka	TOYOTA YARIS 15-2NR-FKE MANUELL 5DR FORDON AVSET	Autodemontering TT AB 0416-511370	4.599 A
4352 5076	W1505352 485 SEK	Subaru XV -23 Spolarpump Baklucka	2,0 l. SUBARU XV (HEV) FB20WVZHPA TH58ADDMAB / VAR	Örebro Bildemontering AB 019-6701200	258 A